



ASBESTOS ANALYTICAL REPORT

ASBESTOS CONTROL PROGRAM LABORATORY
96-05 HORACE HARDING EXPRESSWAY
CORONA, NEW YORK 11368
(718) 595-6309 FAX# (718) 595-6307

ELAP # 11045

TEST METHODS: 1) 40 CFR Part 763, Subpart F, App. A
2) Polarized Light Microscopy plus Stratified Point-Counting Method
3) EPA/600/R-93/116

Incident #: WTC071302
 Inspector : C. LUTCHMEDIAL
 Premise : 15 JOHN STREET
 Boro : Manhattan
 Analyst : E. BRUTUS

Date Collected: 07/13/02
 Received: 07/13/02
 Analyzed: 07/13/02

Client #:

DEP Sample #:	20713/A058001	20713/A058002	20713/A058003
Laboratory #:	20713/638	20713/639	20713/640
Location Sampled:	WESTSIDE ROOF	WESTSIDE ROOF	WESTSIDE ROOF
Color:	BEIGE	GREY	GREY
Homogenous:	Yes	Yes	Yes
Asbestos Present:	Yes	Yes	Yes

Results (%)

Chrysotile	1.8	Chrysotile	1.5	Chrysotile	<1
Cellulose	5	Cellulose	5	Cellulose	15
Fibrous glass	35	Fibrous glass	25	Fibrous glass	20
Matrix	58.2	Matrix	68.5	Matrix	65

Comments:

Reviewed by:

A. A. Heloney
 Laboratory Director

This test report may not be reproduced except with the written approval of this laboratory. The test report relates only to the item(s) listed and does not represent a product endorsement by NVLAP or any other U.S. Government agency.