

SIAC Air Quality, December 2-3, 2001

SIAC 86 Trinity Place, Equipment Repair Workshop, Polychlorinatedbiphenyls in Air Results, 2-3 December 2001

Substance	CAS No.	Results $\mu\text{g}/\text{m}^3$
Arochlor-1016	12674-11-2	<20
Arochlor-1221	1104-28-2	<20
Arochlor-1232	11141-16-5	<20
Arochlor-1242	53469-21-9	<20
Arochlor-1248	12672-29-6	<20
Arochlor-1254	11097-69-1	<20
Arochlor-1260	11096-82-5	<20

SIAC 86 Trinity Place, Computer rack @ Fax, Polychlorinatedbiphenyls in Air Results, 2-3 December 2001

Substance	CAS No.	Results $\mu\text{g}/\text{m}^3$
Arochlor-1016	12674-11-2	<20
Arochlor-1221	1104-28-2	<20
Arochlor-1232	11141-16-5	<20
Arochlor-1242	53469-21-9	<20
Arochlor-1248	12672-29-6	<20
Arochlor-1254	11097-69-1	<20
Arochlor-1260	11096-82-5	<20

SIAC 86 Trinity Place, Console 11, desk area, Polychlorinatedbiphenyls in Air Results, 2-3 December 2001

Substance	CAS No.	Results $\mu\text{g}/\text{m}^3$
Arochlor-1016	12674-11-2	<20
Arochlor-1221	1104-28-2	<20
Arochlor-1232	11141-16-5	<20
Arochlor-1242	53469-21-9	<20
Arochlor-1248	12672-29-6	<20
Arochlor-1254	11097-69-1	<20
Arochlor-1260	11096-82-5	<20

The polychlorinatedbiphenyls (PCBs) samples collected from the SIAC space are all below detectable limits. The polychlorinatedbiphenyls (PCBs) levels in the SIAC space are acceptable.