

Construction Managers
Consultants
Builders

F. J. Sciame
Construction Co., Inc.
80 South Street
New York, NY 10038

Tel: 212. 232 2200
Fax: 212. 248 5313

Sciame

April 29, 2002

R Radhakrishnan, P.E.
Director
Asbestos Control Program
59-17 Junction Boulevard
Corona, NY 11368-5107

RE: 80 South Street, New York


Dear Director Radhakrishnan,

On the morning of September 11, 2001, immediately following the collapse of the Trade Center buildings, the building fans we shut down and air intake and exhaust dampers closed.

Upon returning to the property on September 17, head personnel from F.J. Sciame Construction's staff with extensive experience in the building trades checked the entire building and its systems. No dust/ash was found air conditioning system. System filters were changed and the system restarted on a re-circulated air setting. As a precaution, filters were changed again a few weeks later. A light accumulation of ash remained on the roof upon our return to the building. The roof was hosed down at the time to remove the dust. No other exterior clean-up was conducted outside of the ordinary schedule of maintenance.

I hope this provides the information you required. I can be reached at (212) 232-2200 x164 if you have any further questions.

Sincerely,



John Evans

ENTERED

Construction Managers
Consultants
Builders

F. J. Sciamé
Construction Co., Inc.
80 South Street
New York, NY 10038

Sciamé

R. LADHAKISHAN, P.E.
Asbestos Control Program

55-17 Junction Blvd.

Corona, NY 11368-5107
1373/5108

