

7/2002 15:53 FAX 2129444618

AMBIENT GROUP

013

Ambient Group, Inc.
10 Morris Avenue
Sten Cove, NY 11542
516) 609-0009

ELAP 10865

AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor/Sample Location Description	Analytical Sensitivity	Asbestos Structures/
4055-01	11976	12/10/01	10:47 AM	11th Floor: South Side	LT ANYL SENS	< 0.0045
4055-02	11977	12/10/01	10:48 AM	11th Floor: North Side	LT ANYL SENS	< 0.0045
4055-03	11978	12/10/01	10:49 AM	11th Floor: Central Area	LT ANYL SENS	< 0.0045
4055-04	11979	12/10/01	10:50 AM	11th Floor: East Side	LT ANYL SENS	< 0.0045
4055-05	11980	12/10/01	10:51 AM	11th Floor: West Side	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

1/2002 15:53 FAX 2129444618

AMBIENT GROUP

014

ambient Group, Inc.
 0 Morris Avenue
 Glen Cove, NY 11542
 516) 609-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
 (TRANSMISSION ELECTRON MICROSCOPY - TEM)**

Client: Jack Resnick & Sons, Inc.
Address: 75 Park Place
Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor/Sample Location Description	Analytical Sensitivity	Asbestos Structures/
4056-01	11981	12/10/01	10:52 AM	11th Floor: Elevator Lobby	LT ANYL SENS	< 0.0045
4056-02	11982	12/10/01	10:53 AM	11th Floor: South West Section	LT ANYL SENS	< 0.0045
4056-03	11983	12/10/01	1:20 PM	10th Floor: Central Area	LT ANYL SENS	< 0.0045
4056-04	11984	12/10/01	1:22 PM	10th Floor: West End	LT ANYL SENS	< 0.0045
4056-05	11985	12/10/01	1:24 PM	10th Floor: Central Area	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY

7/2002 15:53 FAX 2129444618

AMBIENT GROUP

0015

Ambient Group, Inc.
10 Morris Avenue
Sten Cove, NY 11542
516) 609-0009

ELAP 10865

**AIRBORNE ASBESTOS STRUCTURES RESULTS
(TRANSMISSION ELECTRON MICROSCOPY - TEM)**

Client: Jack Resnick & Sons, Inc.

Address: 75 Park Place

Project ID: 211658

Field ID Number	Sample ID	Date	Time	Floor/Sample Location Description	Analytical Sensitivity	Asbestos Structures/
4057-01	11986	12/10/01	1:26 PM	10th Floor: South East Corner	LT ANYL SENS	< 0.0045
4057-02	11987	12/10/01	1:28 PM	10th Floor: North East Corner	LT ANYL SENS	< 0.0045
4057-03	11988	12/10/01	1:30 PM	10th Floor: South West Corner	LT ANYL SENS	< 0.0045
4057-04	11989	12/10/01	1:32 PM	10th Floor: North West Corner	LT ANYL SENS	< 0.0045

LT ANYL SENS = LESS THAN THE ANALYTICAL SENSITIVITY