

Asbestos Inspection Report

Premise No. 30 West Broadway					Inspection Date: 08/08/02	
Floor Exterior, 6	Zip 10013	Borough (1) Manhattan	Block	Lot	Squad # N/A	Badge # A019
Inspector Penny Theodorellys		Building Type College		Basis of Inspection WTC Survey		Photos Taken Yes
Contractor's Name Fiber Control				Sample Number N/A		
Address City				Sample Number		
State Zip Phone				Sample Number		
Laboratory Name Warren & Panzer				Owner's Name Dormitory Authority		
Address City				Address City		
State Zip Phone				State Zip Phone		
Contact Person				Time of Inspection from: 10:00 A.M. – 12:00 P.M.		
At the above referenced site, I met and spoke with Narinder Sarin, Larry Goodwan, and Israel Ruiz, Jr. of the Dormitory Authority. Alphonso Plumptre was also present. Representatives of Fiber Control (Action Environmental) were also present and provided equipment for inspection of the exterior façade. The building exterior was examined from the street and the setback on the north side of the building. The south side of the building was draped due to damage to the building sustained as a result of the WTC. The east side of the building was examined from a boom truck operated by Fiber Control. Alphonso Plumptre and I both went up in the boom truck. Inspection of the exterior surfaces disclosed visible accumulations of material on windowsills and windows. The first floor façade on the east side of the building also had significant amounts of debris from the WTC. The exterior bricks have a glaze finish and did not have an accumulation of debris. Hanging scaffolding was present on the west façade and cleaning activities were in progress. Photographs were taken and are attached.						







































