

16 Rector St. is not in
the list

94 Greenwich is on
the list

WTC Visual Survey Form

Premise Address: 116 Rector St - Cleveland		
Block: 53 Lot: 41	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building: Liberty Public Sch.
# of Stories: 4	AKA's: 94 Greenwich	
Building Owner/Management: Name:		Telephone Number: () FAX: ()
Address:		
On Site Contact: Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	Debris	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ 1/2 to 1" ☐ > 1"	
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"	
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ 1/2 to 1" ☐ > 1"	
Facade Description: _____					
Roof					
Debris: ☒ No Visible/Fine Layer ☐ 1/2 to 1" ☒ > 1"					
Description: <i>error</i> Inspected roof of 105 Washington St <i>correct response</i>					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Comments					

Date: 1/26/2002

Inspection Team: Name: CARL
Name: _____

Agency: D&P
Agency: _____

WTC Visual Survey Form

Premise Address: <u>16 Recto St - Closed</u>	
Block:	Residential ☐ Commercial ☒ Name of Building: <u>Liberty Smoke Shop</u>
Lot:	Mix Use ☐ Other ☐
# of Stories: <u>4</u>	AKA's:
Building Owner/Management:	Telephone Number: ()
Name:	FAX: ()
Address:	
On Site Contact:	
Name:	Telephone Number: ()
Building Owner Management Activities	
Interior Survey Performed ☐ Yes ☐ No	
Exterior Survey Performed ☐ Yes ☐ No	
General Clean Up ☐ Yes ☐ No	Locations: _____
ACM Clean Up ☐ Yes ☐ No	Locations: _____
Air Monitoring ☐ Yes ☐ No	Locations: _____
Copies of All Reports and Data Requested ☐ Yes	

Visual Inspection Results:

Facade:			
		Inspected	Debris
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ ½ to 1" ☐ > 1"
Facade Description: _____			
Roof			
Debris: <u>error</u> ☒ No Visible /Fine Layer ☐ ½ to 1" ☒ > 1" <u>correct response</u>			
Description: <u>inspected from roof of 105 Washington St</u>			
Setbacks N/A ☐			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments			

Date: 1/26/2002Inspection Team: Name: CARLAgency: DGP