

10/02/2002 10:10 FAX

008



ATHENICA

ENVIRONMENTAL SERVICES

Tel: (718) 784-7498

Fax: (718) 784-1085

CLIENT: Warren & Panzer Engineers, P.C.

LABORATORY ID #: T02-10-003

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

AVERAGE G.O. AREA (mm²): 0.013838

PROJECT: NYCDER, 143 Fulton Street, NYC

DATE OF REPORT: 10/01/02

DATE OF ANALYSIS: 10/01/02

EFFECTIVE FILTER AREA (mm²): 385

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (l)	G.O.'S ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (struct./cm ²)	TOTAL ASBESTOS AIR CONC. (struct./cm ³)	TOTAL ASBESTOS FILTER CONC. (struct./cm ³)	AIR CONC. FOR STRUCT. 0.55-3µm	AIR CONC. FOR STRUCT. 5-9.1µm	ASBEST. TYPE CHYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-10-003-2695	IWA Right side of WA	1710	4	0.0554	0.0041	<0.0041	<18.07	NA	NA	NA	NA
02	T02-10-003-2696	IWA 1 st middle of WA	1710	4	0.0554	0.0041	<0.0041	<18.07	NA	NA	NA	NA
03	T02-10-003-2697	IWA 2 nd middle of WA	1710	4	0.0554	0.0041	<0.0041	<18.07	NA	NA	NA	NA
04	T02-10-003-2698	IWA 1 st left side of WA	1710	4	0.0554	0.0041	<0.0041	<18.07	NA	NA	NA	NA
05	T02-10-003-2699	IWA 2 nd left side of WA	1710	4	0.0554	0.0041	<0.0041	<18.07	NA	NA	NA	NA

ANALYST
R. Sionkri

LABORATORY DIRECTOR
S. Damparis

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report reflects only the items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

COMMENTS.

4 - During Glove Bag Removal

SEE REVERSE SIDE FOR ANALYSIS INFORMATION