

WTC Visual Survey Form

Premise Address: <u>46 Trinity place.</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					
<u>The Front awning of the closet restaurant contains</u>					
<u>huge accumulations of WTC debris.</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					

Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					
<u>The building manager would not come out to speak to me.</u>					
<u>The secretary told me that "Go ahead do the survey".</u>					
<u>They have received a letter of instructions from DEP.</u>					

Date: 2/28/2002Inspection Team: Name: RAMMOHAN

Name: _____

Agency: DEP

Agency: _____

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail
Report Date 02/22/2002 09:57 AM

Submitted By
Page 1
Service # 412990

Problem BWTC ASBESTOS: WTC (USE COMMENTS)

Address 44 TRINITY PL 1 Aka 81 Greenwich St.

Cross Streets EXCHANGE ALLY
RECTOR ST

Compass Direction
Building ID 10007

Block 00019

Lot 0018

CMBD 101

Location
Area
Sub-Area 101

District
Parcel
of Calls 1

Duration of Call 00:00

Call Date 02/21/2002 16:25

Taken By 7223

SMITH, BRENDON
Responsibility BHZ

BANHAZMAT (AIR,NOISE,HAZ.MAT)
Priority
Scheduled Date
Inspector
Due Date
Asset
Avg Insp Duration
Customer Contact Req
Budget #
Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

Problem Comments
Initial Caller
Last Name
PII
Title MR

First Name, MI
PII
Address
City, State/Province, ZIP/PC
Foreign
Day Phone
PII
Evening Phone
PII
Call Date 02/21/2002 16:25

Reference
Caller Comments

compl requests info. regarding air quality/asbestos info in 44 trinity & 46 trinity. compl can be reached at given phone #. pls contact compl for info.

Inspected
Resolution

By	R AM.	Date	2/28/02	Time	12:30	Code		Date	2/28	Time	1:15
----	-------	------	---------	------	-------	------	--	------	------	------	------

Thurs. 11:30am to 1:30pm

Merlon Mgmt Corp.

(212) 473-6359

44 1/2 First Ave.
NY NY.

Window exterior & ledges contains fine dust. PII cleaned by handford sent clean-up crew. No air testing done. The Complaint sent dust sample & was -ve

46 Trinity contains visible accumulations of WTC debris on facade & awning.