



Phone: 212/234-3130
Fax: 212/234-3381
E-mail: Info@AmNumSoc.Org

THE AMERICAN NUMISMATIC SOCIETY
(FOUNDED 1858 • INCORPORATED 1865)
BROADWAY AT 155TH STREET
NEW YORK · N.Y. 10032

February 21, 2002

Mr. R. Radhakrishnan, Director
Abestos Control Program
City of NY Dept of Environmental Protection
59-17 Junction Boulevard
Corona, NY 11368

Dear Sir:

Reference our building at 140 William Street (96 Fulton Street). Our building was in process of renovation at the time of the September 11th event. Abestos had previously been removed from the building.

The building has been cleaned and all dust removed. The roof is also clean. The building may be inspected at any time, but it is a good idea to call ahead and make sure the superintendent is available.

We are in process of interior renovations and all the windows need cleaning. We plan to clean the windows as soon as we complete our interior renovations.

Please advise if further information is required.

Sincerely,

C. Richard Dodd
Asst. Treasurer

02/20/2002 12:54

February ____, 2002



The City of New York
Department of Environmental Protection

59-17 Junction Boulevard
 Corona, New York
 11365-5107

Joel A. Miele Sr., P.E.
Commissioner

Robert C. Avaltroni
Deputy Commissioner

Bureau of Environmental Compliance
 Tel (718) 595-4418
 Fax (718) 595-4422

Building Owner Name: Richard Dell

Address: 148 William St

NYC
Subject: MS Tanaka

212 234-3130

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:

☒ building facade(s)
☐ setback(s)
☒ roof
☐ other

HE DID NOT INSPECT THE ROOF (NT)

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by February 27, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.



If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan, P.E.
Director
Asbestos Control Program



THE AMERICAN NUMISMATIC SOCIETY
BROADWAY AT 155TH STREET
NEW YORK · N.Y. 10032



Mr. R. Radhakrishnan, Director
Asbestos Control Program
City of NY Dept of Environmental Protection
19-17 Junction Boulevard
Corona NY 11368

