

See 125 Cedar

Gilsenan, Michael

From: Theodorellys, Penny
Sent: Friday, September 27, 2002 8:30 AM
To: Atteloney, Leonard; Radhakrishnan, Krish
Cc: Gilsenan, Michael
Subject: 125 CEDAR STREET -- FW: PAH wipe sample results

-----Original Message-----

From: Benjamin M. Sallemi [<mailto:sallemi15@atc-enviro.com>]
Sent: Thursday, September 26, 2002 12:29 PM
To: Penny Theodorellys
Subject: FW: PAH wipe sample results



R02090549 Cover
Letter.rtf



R02090549
Report.rtf

-----Original Message-----

From: Fred Burkhardt [<mailto:Burkhardt15@atc-enviro.com>]
Sent: Thursday, September 26, 2002 11:58 AM
To: Sallemi15@atc-enviro.com
Subject: FW: PAH wipe sample results

Fred Burkhardt
 Senior Project Manager
 ATC Associates Inc.
 104 East 25 Street
 New York, NY 10010
 212-353-8280
 212-353-8306 (facsimile)
 646-772-1164 (mobile)

Gilsenan, Michael

From: Callahan.Kathy@epamail.epa.gov
Sent: Tuesday, October 29, 2002 9:47 AM
To: Benson, Sam
Cc: Avaltroni, Robert; Gilsenan, Michael
Subject: RE: a newspaper inquiry re deutsche bank

sam, i heard today that there is cleanup work going on at deutsche bank....if this is accurate, it is only a matter of time that we will be asked to comment on it and any implications it may have for area residents. i think we should get the plan and have the appropriate agencies aware and comfortable with what is going on. please see what you can do. thanks. kc

Kathleen C. Callahan
 212-637-3116
 212-637-3115 (fax)

"Benson, Sam"
 <SBenson@OEM.NYC
 .GOV>

To: Kathy Callahan/R2/USEPA/US@EPA
 cc:
 Subject: RE: a newspaper inquiry re

deutsche bank

10/20/2002 09:26
 AM

Good morning:

I'm sorry that I missed the last meetings but I had some scheduling conflicts (I had some OEM-related travel and also took some time off for the holidays). I'll follow-up on Deutsche Bank and get back to you ASAP.

Hope all is well,

S. Benson
 Director
 Health & Medical Preparedness
 New York City Office of Emergency Management
 Phone 718-422-4806
 Fax 718-422-4871
 11 Water Street
 Brooklyn, NY 11201

Gilsenan, Michael

From: Smyth, Virginia
Sent: Tuesday, October 29, 2002 11:02 AM
To: Gilsenan, Michael; Radhakrishnan, Krish
Subject: FW: Contact

FYI

-----Original Message-----

From: Chacon, Emily [mailto:Emily.Chacon@fema.gov]
Sent: Tuesday, October 29, 2002 10:44 AM
To: 'virginias@dep.nyc.gov'
Subject: Contact

Hi Virginia,

I'm still looking for a contact for the building owner at 93 Nassau. It probably is not a Public Assistance issue, so I'm trying to find someone who knows about the requirements for the other FEMA programs. I'll get the information to you as soon as I can.

Thanks,

E

Emily Chacon
FEMA Project Officer
80 Centre Street
Third Floor
New York, NY 10013
Ph: 212-693-7451
F: 212-667-8987

Gilsenan, Michael

From: Fenves, Carol
Sent: Wednesday, October 30, 2002 8:40 AM
To: Smyth, Virginia; Gilsenan, Michael
Subject: WTC Change Orders

All four change orders for the cleaning contracts have now been registered. Please submit any payment requests that you have to Andy Moss. thanks.

Gilsenan, Michael

From: Theodorellys, Penny
Sent: Wednesday, October 30, 2002 11:43 AM
To: Radhakrishnan, Krish
Cc: Gilsenan, Michael
Subject: 125 Cedar Street, Apartment 7S

The back panels (pieces of loose fitting sheet rock) were removed from the bookshelf without removing the shelves or vertical wood supports.

The screws and the wood from the back support were removed, while I observed and assisted. No debris was observed during the removal. The shelving units themselves cannot be removed without damage. A few of the shelves were removed in an attempt to dismantle the unit, but the glue created splits in the wood and breakage of the trimming. The back wall was HEPA vacuumed and wet wiped repeatedly as was the in place shelving. There is a gap behind the shelves and the rear sheet rock wall. The pieces of removed wood were also HEPA vacuumed and wet wiped.

I was onsite and watched the entire re-cleaning of the bookshelf from start to finish. The cleaning was performed by three handlers and was complete and thorough. No debris was observed during the re-cleaning procedure.