

**Gilsenan, Michael**

---

**From:** Atteloney, Leonard  
**Sent:** Tuesday, July 16, 2002 9:34 AM  
**To:** Gilsenan, Michael (ex)  
**Cc:** Radhakrishnan, Krish  
**Subject:** New York City Department of Environmental Protection

**Importance:** High



wrnpnzrwtc3.doc

**THE CITY OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF ENVIRONMENTAL COMPLIANCE**

**To:** Mike Nolan, Project Manager  
Warren & Panzer Engineers, P.C.

**From:** Leonard Atteloney, Director of Laboratory Services  
Bureau of Environmental Compliance

**Date:** July 15,2002

**Topic:** Laboratory Reports and Chain of Custody Forms to be corrected

\*\*\*\*\*

The following laboratory reports and chain of custody sheets have been reviewed and found to be incorrect:

ATC Group # s:

- 1) 8400 – The chain of custody has “PCM 7400” circled instead of “TEM AHERA.”
- 2) 8423 - The chain of custody needs to be faxed again due to misfeed.
- 3) 8426 – The chain of custody seems to reads “10 Cordlandt” and the report reads “ 10-12 Courtlands Street.”
- 4) 8411 – The lab report is missing results for samples # 11, 12 and 13.
- 5) 8457, 8416, 8445, 8493 – The chain of custody sheets and lab reports reads “156 Williams Street instead of “ 156 William Street.”
- 6) 8482 - The address on the lab report reads “60 Pinest” It should read “60 Pine Street.”
- 7) 8483 – The address on the lab report reads “ 60 Pune Street.” It should read “ 60 Pine Street.”
- 8) 8447,8449 – The address and report list “ Read St” instead of “Reade St”

Please have these reports and chain of custody sheets corrected and resubmit by August 2,2002 with affidavits explaining the reasons for the revised reports and chain of custody sheets. The deadline for submitting items requested as per the Memo dated July 5,2002 will be extended to July 29,2002.

Please be advised that failure to submit requested documents and revised chain of custody and lab report sheets and may delay the processing of invoices.

c: M. Gilsenan, Asst. Commissioner BEC  
K. Radhadkrishnan, Director Asbestos Control Program