

231.020

John T. Dwyer
Consentini Associates
2 Pennsylvania Plaza
New York, New York 10121

May 7, 1982
Re: Intrepid Museum Project
Pier 86 at W 46 Street
Borough of Manhattan

Dear Mr. Dwyer:

In answer to our previous letter of March 2, 1982 we secured detailed drawings indicating the type of building structure to be located over our existing double barrel 6'-6" x 8'-6" sewer outfall. Some structural data is included on the drawings.

On March 12, 1982 a letter was received from the Intrepid Museum Foundation signed by Robert P. Bisaccia, the Director of Operations. The letter was a request that our personnel inspect the existing double barrel sewer outfall mentioned above.

The inspection was made & indicated some adverse findings. It was recommended that the sewer be rehabilitated. We are currently writing to our Division of Sewer Maintenance to formally request the rehabilitation of the existing sewer.

We will need further information in order to ascertain how the structure may affect our sewer. We would appreciate receiving a copy of the foundation design calculations for the structure, the ticket Office & Utility Building, indicating the total loading on the foundation & how the designer arrived at sizes of concrete members & size spacing of reinforcement. An SD 142 application for the project is being reviewed and will go no further until the information requested

is reviewed and it is determined that there will be no adverse structural effects on the sewer due to the building being erected atop it.

Very truly yours

FREDERICK NOVOTNY, CHIEF
Division of Sewer Regulation
& Control
(Bureau of Sewers)

cc: Di Martino
Novotny
Frag
Layko
Lee
Lanzano
Suspense

REL/ep