

OPERATIONS

TIME OF ARRIVAL

BF-24 (12/8)

REPORT -- STRUCTURAL FIRE

[illegible][illegible]

BF-24

ADDRESS						BUILDING		DEFECTIVE DETECTOR		
BORO	NUMBER (INCL HYPHEN)	SUFFIX	PREFIX DIRECTION	STREET NAME	TYPE	SUFFIX DIRECT	STORIES	AREA	BRAND	SERIAL NO.
17			WT C				47	200		
115			126				152	161	162	191

192

NAME OF OCCUPANT

211

212

229

244

254

ROOM/APT

LEFT IN CHARGE

BADGE NO.

YR.

MAKE

SERIAL NUMBER

POWER

ITEM

EQUIPMENT INVOLVED IN IGNITION

[illegible]

OPERATIONS

UPON ARRIVAL AT BOX 8092 FOUND RUBBISH FIRE IN ROOM C-2 (STORAGE ROOM).

UNITS OPERATED AS FOLLOWS:

E-10 TOOK POSITION, HOOKED UP TO HYDRANT, STRETCHED LINE AND STOOD FAST.

MADE NECESSARY SEARCH AND EXAMINATION, LOCATED FIRE AND EXTINGUISHED WITH HAND EXTINGUISHER, OVERHAULED, CHECKED FOR EXTENSION, FOUND NEG.

പ്
മ്

01

D.C.

Bc Richard Prunty

TYPE FULL NAME

TIME OF ARRIVAL

TYPE FULL NAME
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

TIME OF ARRIVAL

PAGE

1

DIV.

DIV.