




ENGINE COMPANY 10 -- TEN HOUSE

Oct. 30, 1998

To:	William Balich	Battalion 01 Chief
From:	Gene Kelty	Capt. Eng. 10
Re:	7 World Trade Center - Fuel Tank	

As per your memo, A visit was made to 7 W T C for inspection. Mr. Carrigan, the Fire Safety Director directed us around the building. The following items were addressed:

1. The tank is approximately 6,000 gal. not 10,000 as indicated on the A-8 (as per Mr. Carrigan). Mounted at the ceiling level and empty.
2. The room that this tank is located within, also has access to the low rise elevator pits.
3. In this room is located a standpipe outlet.

My main concerns is that, any product loss would land on the floor, since this tank is located at the ceiling level with steel structural beams for support. This could cause a problem since the two elevator rooms are located here and any fire in this room would negate access to the elevator pits as well as the use of the standpipe outlet which is located at the front of the room.

FIRE DEPARTMENT REFERRAL REPORT

10/12/98

DATE:

Zip 10038

Div 1	Batt 1	Co E-10	D.O. 1
----------	-----------	------------	-----------

Premises Location 7 World Trade Center

Boro Manhattan

	Bldg. Owner
xx	Bldg. Agent
	Occupant

Name Port AuthorityType of Occupancy/Bldg COMMMailing Address SameBoro ManhattanZip 10038

ITEM NUMBER	FILL IN ITEM NO.	NATURE OF REFERRAL	ROOM/FLOOR	LOCATION
1-E		(Defective/Improper) Electrical Wiring		
2-F*		No Grease Filter or Extinguishing System		
5-B		Unenclosed Stairway		
6-B		No Certificate Of Occupancy		
7-B		Unenclosed (Hository) Shaft		
8-B		No Secondary Means of Egress		
9-B		Defective (Cornice/Brickwork/Masonry)		
10-B		Hole in (Wall/Ceiling/Floor/Fire stopping)		
11-B		Defective Chimney		
12-B		Structural Stability Affected		
13-B		Boiler Room Not Enclosed F.O. Acct. No.		
14-B		No Occupancy Sign Posted		
15-B		No Floor Load Sign		
16-B		Illegal Occupancy		
17-B		No Protection for Metal Floor Supports		
19-B		Water Leak in Vicinity of Electrical Wiring		
72-F	72-F	No Fire Dept. Permit for Fuel Oil	1	Buried Tanks & lobby
21-F		No Interior Fire Alarm System		
22-F		No Fire Drills		
27-F*		Defective Interior Alarm Box		
29-F		Sprinkler System Unserviceable		
32-B*		(Primary/Secondary) Means of Egress Substandard		
37-B		No (Exit Light Fixture/Exit Sign) for Egress		
38-B*		Unused (Shaft/Duck) Not Sealed Closed		
	72-F	ABOVE GROUND PIPE COR. D.E. TANK		
		BEING INSTALLED IN LOBBY WITH ACCESS		
		TO B-ELEVATOR COR. DURS + PIT. + STAND PIPE		
		OUTLET		

NOTE: Forward separate A-8 reports for Comb. items; Fire Prev. items, each Dept. Concerned
If Combustible Violations are involved, please provide Account Number(s)

Remarks: Possible illegal Fuel Oil tank in lobby

Found By-Signed <u>William P. Blach</u>	Rank <u>BC</u>	Unit <u>Bn-1</u>	Initials of Officer on Duty <u>WPB</u>
Company Commander <u>Thom Hany</u>	Rank <u>BC</u>	Unit <u>BN-1</u>	Date <u>10/12/98</u>
For Bur. Of F.P. Only	Referred to: Dept.	Date	Report No.

RETURN TO: FIRE DEPARTMENT-BUR. OF FIRE PREVENTION, 250 LIVINGSTON ST. BKLYN N.Y. 11201

TO BE FILLED IN BY F.D. INSPECTOR:				Div	Batt	Co	D.O.	Date
Agent	Name	Port Authority		Premises Location		7 World Trade Center		
Disposition								Report No.

Signed _____ Dept. _____ Date _____

Important Message



Time: _____ Date: 10/12/98
 For: ENGINE 10
 From: 361 PLANT
 Telephone: 361/39/42/43/44

- | | |
|--|--|
| ☐ Telephoned | ☐ Please call |
| ☐ Wants to see you | ☐ Will call again |
| ☐ Returned your call | ☐ URGENT |
| ☐ Was here to see you | |

Message: FYI + FOLLOW UP
INSPECTION ON NEXT
BI

Taken by: BC Black

Post-it® 7679-4 ©3M 1993