

BF-24 (12/8 530-R02B-N

B-F-24

ADDRESS

OPERATIONS

E-10 TOOK POSITION, HOOKED UP TO HYDRANT, STRETCHED LINE AND STOOD FAST.

L-10 MADE NECESSARY SEARCH AND EXAMINATION, LOCATED FIRE AND EXTINGUISHED WITH HAND EXTINGUISHER. OVERHAULED, CHECKED FOR EXTENSION, FOUND NEG.

Bc Richard Prunty

TYPE FULL NAME

ADMINISTRATIVE COMPANY

REPORT LISTING - COMPANY OFFICER

MONTH DAY YR BATT. REVISED
 07 19 95 01 10



FROM TO

LISTING NOS.

BATTALION CHIEF REVIEWING

COMP. NO.	TIME RECEIVED	DURATION	HOW REPORTED	LOCATION		REPORT NUMBER	INCIDENT NUMBER	RESP.		TYPE OF INCIDENT	FACTOR	HAZ. MAT.		VEH. TYPE	PTS. 106
				ALARM BOX	ADMIN. COMPANY			E	L			CLASS	AMT.		
1	15100040	10	01008350	10	0835010	0485	110134000								
ADDRESS				STREET NAME				TYPE		SUFFIX		COMPANIES		PTS. 106	
1 VESOV				WEST				ST				501002701002		LEFT IN CHARGE (APT.)	
YR.				MAKE				VIN.		143		124		143	
2	94	1000				1F05S34M5RHB63816									
3	86	1000				CT2040 NJ									
4															
5															

LISTINGS

FROM TO

OFFICER IN COMMAND

W. Kearney

HOW REPORTED

10 Telephone
 20 Street Box - Manual
 21 CL-3 - Manual
 30 CL-3 - P.F.A.
 31 CL-3 - Valve P.F.A.
 32 CL-3 - Auto. P.F.A.
 50 Verbal
 80 Pre-Recorded Telephone
 81 CL-3 - E.R.S.

INITIAL ALARM

0 Spec. Call -
 other than Eng. Only
 1 Box
 5 Spec. Call -
 Eng. Only
 9 Still

TYPE OF INCIDENT

10 Water Leaks
 13 Collision Vehicular Incident
 16 Incinerator Emergencies
 17 Fuel Oil & Gasoline Leaks
 18 Leaks, Illum. Gas, Foam Vapor
 20 On-Burner Emergencies
 22 Power Electrical
 25 Smoke Cond., Odors, Fumes
 26 Sprinkler

TYPE OF INCIDENT

27 Steam Discharge
 28 Defective Alarm Device
 29 Smoke Detector
 30 Defective Alarm (Sprinkler)
 35 ADV. Fires
 38 Brush Fires
 41 Outside Rubbish Fires
 45 Manholes

TYPE OF ACTION TAKEN

1 Extinguishment
 2 Rescue
 3 Investigation
 4 Remove Hazard
 5 Standby
 6 Salvage
 7 First Aid

REPORT — STRUCTURAL FIRE

42F-B

OPERATIONS

Responded to box 84, reported explosion on the 44th fl. address 7WTC, and upon further investigation found electrical explosion on 41st. fl. with injured civilian K. Wong Kinsing male, age 30 with burns on arm and face. EMS #1790 treated patient and removed to N.Y. hospital. Co's operated VIZ:

2-10 stretched line and stood fast
2-10 assisted EMS in administering to injured, checked fls. 42, 43, & 44 condition neg. and then up
2-10 checked fls. 41 & 42 and found electrical switch on 41st. fl. which had caused explosion, fire
2-10 had extinguished itself and power was turned off, performed necessary VES and overhaul and up

BC	<u>John J. Spillane</u>	<u>DC</u>	<u>DIV</u>	PAGE <u> </u> OF <u> </u>
	<u>John J. Spillane</u>	<u>TYPE FULL NAME</u>	<u>TIME OF ARRIVAL</u>	<u>GOLD—ADMINISTRATIVE COMPANY</u>
	<u>BY 0941</u>	<u>TYPE FULL NAME</u>	<u>TIME OF ARRIVAL</u>	<u>PINK—REFERRAL</u>
	<u>WHITE—FIRE RECORD</u>	<u>TYPE FULL NAME</u>	<u>TIME OF ARRIVAL</u>	<u>YELLOW—BATTALION</u>

REPORT — STRUCTURAL FIRE

[illegible]

OPERATIONS

Upon arrival at Box 84 found fire in construction shanties on the 3rd floor. Transmitted 10:76 and 10:41-1. Units operated VIZ:
E10-Stretched line from standpipe and extinguished fire.
L10-Found sprinklers and in operation. Shut down sprinklers and made necessary search, ventilation and overhauled as required.
E7-assisted E10.
E4-Stretched line to 4th floor. Stood fast.
E6-assisted E4.

BC	<i>Rudolph S Quatrone</i>	BIN <i>BB-7</i>	PAGE 1 OF 2
<i>Rudolph S Quatrone</i>		DC _____	DIV _____
Type Full Name	Type Full Name	Type Full Name	Type Full Name
WHITE—FIRE RECORD	YELLOW—BATTALION	PINK—REFERRAL	GOLD—ADMINISTRATIVE COMPANY

Reason for 10:41-1
Found 2 separate fires with no possible
indication of reason for fire.

REPORT — ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		INCIDENT NUMBER	IGNITION				STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION					
MONTH	DAY	YEAR	HOUR	MINUTE	BOROUGH	BOX NUMBER	BUILDING NO.		DATE OF ARRIVAL	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	CONSTRUCTION	USE	STATUS	FLOOR CODE	OCCUPANCY	AREA CODE	MANNER	OCCUPANCY	REVISED REPORT
6	05	20	88	0038	1	0084	0008		3	98	97	97	97	1	591	1	03	50	39	00	99	
1	2		8	12		17		23						32		37			43		47	

ROAD	NUMBER (INCL. HYPHEN)	SUFFIX	PREFIX	DIRECT	STREET NAME				TYPE	SUPPLY	DIRECTION
1	7				WTC						
57					68				88		93

DAMAGE				DETECTORS				
SPR. PERFORMANCE	% DAMAGED	FLAME	SMOKE	WATER	PRESENT	TYPE	POWER	PERFORMANCE
1	1	6	6	1	1	2	1	
48		53						

OCCUPANT (Driver)				ROOM/APT.			
94			113				

IF MOBILE PROPERTY		TYPE	YR.	MAKE	MODEL	V.I.N.	LICENSE	STATE	DM
189	195	201	207	213	219	225	231		
7	010	20	73	001	20	7	008	20	
237	UNIT	PTS.	243	249	255	261	261	273	279

STORIES		AREA	
WIDTH	LENGTH		
48	0400	0400	
114		123	

OPERATIONS

Operations as follows;

L8-Assisted L10 Made primary and secondary search of 5-10,11,12. Then up.
 L1-Made search and examination of the 4th floor. Then assisted L8 in the examination of upper floors. Then up.
 Batt 4-Supervised E10 and L10 on fire floor.
 Batt 2-Supervised E4 and E6 and L1 on floors above fire.
 PCU- SOP
 MSU- SOP
 E3- Stood fast.
 Batt 6- Stood fast.

BC Rudolph S. Quatrone Bn-1

B.N.

DC _____ DIV _____

Rudolph S. Quatrone

0043

TYPE FULL NAME

TIME ARRIVED

TYPE FULL NAME

TIME ARRIVED

PAGE

OF

2

2

012

REPORT — STRUCTURAL FIRE

[illegible]

OPERATIONS

Upon arrival to box 84 found the following conditions, fire was on the 6 floor in four separate areas. Companies operated V.L.I. 141 raised tower ladder to gain entry and extinguish with cans. E-7 and E-8 stretched line via outside building to E-10 on the fire floor, E-10 completed extinguishment.

1-10 assisted by L-1 in search checked the floors below then up, above
 1-10 assisted by L-1 in search checked the floors below then up, above

BC	J. Spillane		PAGE	
	John J. Spillane	BATT 2940	OF	1
		TYPE FULL NAME	DIV	
		TIME OF ARRIVAL		
		WHITE—FIRE RECORD		
		YELLOW—BATTALION		
		PINK—REFERRAL		
		GOLD—ADMINISTRATIVE COMPANY		

BF 25 (1-80)

REPORT—TRANSPORTATION FIRE, NON STRUCTURAL FIRE OR EMERGENCY.

TYPE REPORT		INCIDENT LOCATION		DATE AND TIME ALARM RECEIVED				INCIDENT DURATION		BOX LOCATION		REPORT		COS RESP.					
COMMUNITY BOARD	ADDM. COMPANY	BLOCK NUMBER	MONTH	DAY	YEAR	HOUR	MINUTE	SECONDS	HOW REPORTED	INITIAL ALARM	HIGHEST ALARM	BOROUGH	BOX NUMBER	REPORT NUMBER	ENGINE BATTALION	PADDER NUMBER	ENG. SQ. NUMBER	LAUNCH	
4	01	5 010	0026	04	04	87	13	16	01	30	2	1	1	0084	0054	01	113	01	1

AIDED AND CASUALTIES				IGNITION				SPECIAL USE			NAME OF OCCUPANT (Driver)						
CIVILIANS				TYPE INCIDENT				TYPE INCIDENT			ROOM, APT. NO.						
EVACUATED	FIRST AID	INJURED	KILLED	UNINFORMED	EXTINGUISH CODE	TYPE INCIDENT	TERM STAGE	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	FACTOR	SMOKE DETECTORS	1	2	3	

ROOM, APT. NO. **Sgt. Smolen P.A. Police**

LEFT IN CHARGE

NUMBER (INCL. HYPHEN)		STREET NAME		TYPE		EQUIPMENT INVOLVED IN IGNITION		MAKE		MODEL		SERIAL NO.		POWER	
7		WTC													

ITEM		YR.		MAKE		MODEL		SERIAL NO.		LICENSE		STATE	

OPERATIONS

Units responded to 7 WTC for a scaffold located on the outside of the 24th floor which had to be secured to the building, companies operated as follow;

L-10 responded to 24th floor and broke window out to secured scaffold.

E-7 responded to Vessey and West St. to prevent pedestrians and vehicles from entering area while window was being broken, scaffold secured both companies took up leaving P.A. Police in charge.

B.C. John J. Spillane D.C. 4318 DIV. 1

TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL

ADMINISTRATIVE COMPANY

BF 24 (1/80)-175M-628551 (83)

REPORT — STRUCTURAL FIRE

INCIDENT LOCATION				DATE AND TIME ALARM RECEIVED				INCIDENT DURATION				BOX LOCATION				REPORT				COS. RESP.			
ADMIN. COMPANY				YEAR				HOURS				BOROUGH				FILING				LADDER			
BLOCK NUMBER				MONTH				MINUTE				INITIAL ALARM				REPORT NUMBER				ENGINE NUMBER			
101				06-25-06				00:20				101				0332				01 572 02 2			

AIDED AND CASUALTIES				EXTINGUISHMENT				IGNITION				STRUCTURE				AREA FIRE ORIGIN				FIRE EXTENSION				SPECIAL USE			
CIVILIANS				STAMPED LINES USED				MATERIAL TYPE				STATUS				FLOOR CODE				OCCUPANCY				SMOKE DETECTORS			
UNFURNISHED				SPRINKLER				HEAT FORM				CONSTRUCT				BLDG. DAMAGE				MANNER OF				NO. BLDGS.			
KILLED				STANDPIPE				EQUIP INVOLVED				USE				FLOOR CODE				OCCUPANCY				OCCUPANTS			
INJURED				NO OPEN				TERM STAGE				MATERIAL FORM				FLOOR CODE				OCCUPANCY				OCCUPANTS			
FIRST AID				CODE				EQUIP INVOLVED				MATERIAL TYPE				FLOOR CODE				OCCUPANCY				OCCUPANTS			
EVACUATED				UNFURNISHED				EQUIP INVOLVED				MATERIAL TYPE				FLOOR CODE				OCCUPANCY				OCCUPANTS			
00 00 00 00				00 00 00 00				00 00 00 00				00 00 00 00				00 00 00 00				00 00 00 00				00 00 00 00			

STREET NAME				BUILDING				AREA			
7 World Trade Center				110				250 x 250			
103 108				110				250 x 250			

NAME OF OCCUPANT				ROOM, APT. NO.				EQUIPMENT INVOLVED IN IGNITION			
Yieldman Bros. Inc.				110				YR. MAKE MODEL S.N. POWER			
103 108				110				187			

OPERATIONS

Upon arrival found alarm for fire involving scaffold in the above building under construction.

Eng. 7 stretched booster line & extinguished fire.

Lad. 10 Used power saw, made necessary examination & overhaul.

B.C. Kenneth P. Markgraf 1st D.C. 1102 DIV. 1 OF 1

TYPE FULL NAME Kenneth P. Markgraf TIME OF ARRIVAL 1102 TIME OF ARRIVAL

BF-25 (1/80)

REPORT-TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY.

TYPE REPORT		INCIDENT LOCATION		DATE AND TIME ALARM RECEIVED				INCIDENT DURATION		HOW REPORTED		BOX LOCATION		REPORT		EDS RESP.	
COMMUNITY BOARD	ALPHA COMPANY	BLOCK NUMBER	MONTH	DAY	YEAR	HOUR	MINUTE	HOURS	MINUTES	INITIAL ALARM	HIGHEST ALARM	BOX NUMBER	REPORT NUMBER	PLUNG SALTATION	ENGINE NUMBER	ENGINE MACHINE	
4	01	5 010	0026	07	21	86	2056	01	25	2	0	1	0	0084	0292	01 075	02 3

AIDED AND CASUALTIES				IGNITION		SPECIAL USE											
CIVILIANS	THREATENED	FIRST AID	INJURED	KILLED	UNINFORMED INJURED	EXTINGUISHER CODE	TYPE INCIDENT	ITEM STAGE	EDDIP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	FACTOR	SMOKE DETECTORS	1	2	3
00	00	00	00	00	00	03											

NAME OF OCCUPANT (Driver) _____

ROOM APT. NO. _____

LEFT IN CHARGE _____

NUMBER (INC. HYPHEN)	STREET NAME	TYPE	USED TRUCK
7	World Trade Center		

Equipment Involved in Ignition	MAKE	MODEL	SERIAL NO.	POWER

If Mobile Property	MAKE	MODEL	SERIAL NO.	LICENSE	STATE

UNIT	PTS	234	240	246	252	258	264	270	276
5	010	02	7	010	02				

OPERATIONS

Responded to phone alarm report of elevator emergency. Upon arrival Found that outside elevator x hoist had buckeled in 3rd floor . and possible danger of collapse. Police was on scene ,streets were closed off so pedestrians and vehicles were barred from area. . Heydt Const. Elevator mechanic was on scene, Building Dept. Was called to scene, Chief Inspector Joe Walsh responded from Bldg. Dept. Port Authority police was left on scene. Lt. George Tell .

Engine Co. 10 - Stretched and stood fast.
Ladder Co. 10- Confirmed no one was in bldg. Closed off area.

B.C.	NAME	1st	D.C.	NAME	DIV	OF
	Rudolph S. Quatrone					
	<i>Rudolph S. Quatrone</i>	20:59				
	TYPE FULL NAME	TIME OF ARRIVAL		TYPE FULL NAME	TIME OF ARRIVAL	

ADMINISTRATIVE COMPANY