

BF-24 (7/83)-175M-608551 (83)

REPORT -- STRUCTURAL FIRE

TYPE REPORT		INCIDENT LOCATION		DATE AND TIME ALARM RECEIVED				INCIDENT DURATION		INCIDENT REPORTED		BOX LOCATION		REPORT		COS. RESP.				
COMMUNITY	ADDM	BLOCK	MONTH	DAY	YEAR	HOUR	MINUTE	SECONDS	MINUTES	INITIAL ALARM	HIGHEST ALARM	BOX NUMBER	REPORT NUMBER	FLAME	BATTALION	SQUAD	ENGINE			
1	01	5	010	0026	06	25	86	03:20	03	00	2	0	3	1	0084	0329	01	572	14	7

AIDED AND CASUALTIES				EXTINGUISHMENT		IGNITION		STRUCTURE		AREA FIRE ORIGIN		FIRE EXTENSION		SPECIAL USE																			
CIVILIANS																																	
EVACUATED	FIRST AID	INJURED	KILLED	UNINFORMED	INJURED	CODE	SPRINKLER	NO OPEN	STAMPED	LINKS USED	TERM	STAGE	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	FACTOR	CONSTRUCT	USE	STATUS	BLDG DAMAGE	CONTS DMSG	FLOOR CODE	RM/AREA CODE	OCCUPANCY	MANNER OF	DECLINANT'S	NO. BLDGS	SMOKE DETECTORS	1	2	3	
01	00	00	00	05	8	00	02	3	15	56	69	75	46	1	15	6	1	1	00	10	58	08	01	2									

NUMBER		STREET NAME		TYPE		BUILDING		AREA	
7		World Trade Center				47		250 x 250	

NAME OF OCCUPANT: Under Construction
ROOM, APT. NO.:
LEFT IN CHARGE: Gen. Supt. Fishman Const. Corp.

EQUIPMENT INVOLVED IN IGNITION

UNIT	PTS	ITEM	YR	MAKE	MODEL	S/N	POWER							
5	010	25	7	010	30	5	007	30	5	006	30	7	001	30

OPERATIONS

Upon arrival found alarm for fire in watchman's shack, communicating to building materials & to the outside construction elevator up to a height of 13 floors of the 47 story building under construction. Fire also extended across pedestrian bridge to 6 World Trade Center (Exp.#1) & ignited building scaffolding & the heat damaged a large window on 1st floor. Heat also damaged windows on the 2nd & 5th floors of 210 Washington St. (Exp.#2). First arriving units were confronted with a large body of fire due to delayed alarm, watchman tried to extinguish the fire he accidentally started.

B.C. Kenneth P. Markgraf 1st D.C. Henry C. Reyes 1st
 TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL
 Kenneth P. Markgraf 0324 Henry C. Reyes 0329

 PAGE
 1 OF 5

REPORT—ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		IGNITION				STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION							
MONTH	DAY	YEAR	HOUR	MINUTE	BOROUGH	BOX NO.	BUILDING NO.	TERM STAGE	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	CONSTRUCT.	USE	STATUS	BLOS. DAMAGE	CONT'S EMER.	FLOOD CODE	HMJAREA CODE	OCCUPANCY	MANNER OF	OCCUPANCIES	
6	06	25	86	0320	1	0084	02							1	15	1							

NUMBER (INCL. HYPHEN)		STREET NAME		IF MOBILE PROPERTY	
6		World Trade Center			

YR.	MAKE	MODEL	79 SERIAL NO.	LICENSE	STATE

UNIT	PTS.	195	201	207	213	219	225	231	238														
5	004	12	5	055	12	5	024	12	1	001	20	7	008	20	6	001	00	5	015	00	5	207	22
5	009	22	5	330	00	5	005	10	5	033	02	5	018	12	5	028	02	7	006	00	7	018	10

OPERATIONS

Units had to make long hose stretches for water supply do to hydrants out of service & others within the area of high radiant heat, could not be approached. Wind conditions: 15-20 MPH.

Units operated & extinguished fire in the following manner.

Signal	Time	By Order of
10-75	0320	Eng. 10
10-22	0321	Eng. 10
10-33	0337	Batt. 1

Eng. 10 Transmitted signal 22-84, used multiversal nozzle on fire with booster water. Stretched line into Tower Lad. 1. Used inline water pumping & Eng. 4 as water supply. Stood fast on 4th floor.

Eng. 7 Used inline pumping, used multiversal nozzle on fire. Stretched line & operated on fire.

Eng. 6 Used inline pumping, stretched line from Eng. 7 & operated on fire. Stretched another line & made washdown.

Lad. 10 Forced entry to building, made necessary search, examination & overhaul of floors 1 - 15.

Lad. 1 Operated tower ladder pipe on main body of fire. Protected apparatus with booster stream. Made necessary search, examination & overhaul of 5th floor of fire building.

Res. 1 Made search of fire building, & survey of standpipe sys.

R.C.	Kenneth P. Markgraf	1st	D.C.	1st	PAGE
		BN.		DIV.	OF
	Kenneth P. Markgraf	0324	Henry G. Reyes	0320	2
	TYPE FULL NAME	TIME OF ARRIVAL	TYPE FULL NAME	TIME OF ARRIVAL	5

ADMINISTRATIVE COMPANY

REPORT — ADDITIONAL DATA**STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY**

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		IGNITION				STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION							
MONTH	DAY	YEAR	HOUR	MINUTE	SECOND	BOX NO.	BUILDING NO.	FIRM	STAGE	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	CONSTRUCT	USE	STATUS	ROOF DAMAGE	CONT'S DAMAGE	FLOOR CODE	RAJAHRA CODE	OCCUPANCY	MANAGER OF	OCCUPANCIES
6	06	25	06	03	20	1	0084	03				1	15	1	1								

NUMBER (INC. HYPERM)		STREET NAME		IF MOBILE PROPERTY	
YR	MAKE	MODEL	SERIAL NO.	LICENSE	STATE
210		Washington	St		

UNIT	PTS.	195	201	207	213	219	225	231	236
7	119	20	7	131	10				

OPERATIONS

Eng. 4 Relayed water to Eng. 10. Stretched handline from Eng. 4 to 6 World Trade Center & extinguished fire in lumber outside. Forced door for access to 6 World Trade Center.

Eng. 55 Stretched line into Eng. 7. Made examination of Exp.#2 (210 Washington St.).

Eng. 24 Assisted Eng. 5 in stretching line to 6th floor of fire building.

Lad. 8 Made necessary search & examination of floors 1 - 5 of Exp.#2 (210 Washington St.).

Batt. 4 Supervised operations of Eng. 5, Eng. 6, Eng. 10, Lad. 10, Lad. 18, & Res. 1 in fire building.

Saf. Batt. Observed unit operating procedures.

Mar. 1 Standby at foot of Liberty St.

Eng. 15 Warned Mar. 1.

Eng. 207 (Max Water) Supplied Tower Lad. 119 .

Eng. 9 (Sat. 1) Stretched 4 1/2" hose to front of fire building. Operated monitor on outside elevator fire. Supplied lines to Eng. 18 & Tower Lad. 1 from manifold.

FCU. 1 Established Field Headquarters.

Eng. 330 (Sat. 3) Stood Fast.

B.C. Kenneth P. Markgraf 1st BN. D.C. Henry G. Keyes 1st DIV.

Kenneth P. Markgraf 0324 Henry G. Keyes 0329

TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL

ADMINISTRATIVE COMPANY

REPORT — ADDITIONAL DATA**STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY**

TYPE REPORT		DATE AND TIME ALARM RECEIVED					BOX LOCATION		IGNITION				STRUCTURE		AREA OF ORIGIN			FIRE EXTENSION				
MONTH	DAY	YEAR	HOUR	MINUTE	SECOND	BOX NO.	BUILDING NO.	TERM. STAGE	EDUP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	CONSTRUCT	USE	STATUS	BLOB DAMAGE	CORPUS DAMAGE	FLOOR CODE	RM/AREA CODE	OCCUPANCY	MANNER OF	OCCUPANCIES
6	06	25	26	0320	1	0084																

NUMBER (INCL. HYPHEN)		SUFFIX	STREET NAME	TYPE	SUFFIX	IF MOBILE PROPERTY

YR.	MAKE	BI	SI	MODEL	79 SERIAL NO.	LICENSE	STATE

UNIT	PTS.	198	201	207	213	219	225	231	236

OPERATIONS

Eng. 5 Stretched handline from Eng. 6 pumper & operated on 4th & 6th floors of fire building.

Eng. 33 Stood fast on 13th floor of fire building.

Eng. 18 Stretched handline from Eng. 10 & operated on watchmans shack & outside building materials.

Eng. 28 Assisted Eng. 5 in stretching handline to 4th floor of fire building.

Lad. 6 Stood fast.

Lad. 18 Assisted in stretching handline & made necessary overhaul on 2nd & 5th floors.

Lad. 119 Operated Tower Lad. Pipe on burying exterior elevator. Made examination & overhaul of exterior of building.

Lad. 131 Made examination of 12 & 13th floors.

Batt. 2 Supervised Eng. 5, Eng. 33, Eng. 24, Lad. 131 on 5th & 13th floors.

Amb. 1 Stood Fast.

Mask Ser. Stood Fast.

Injury to Members:

FF Jessamine ,	Eng. 7	Laceration/Chin
FF Meyers ,	Eng. 7	Contusion Back
FF Demic,	Lad. 131	Sprain Left Knee

B.C. <i>Kenneth F. Markgraf</i>	1st	D.C. <i>Henry G. Keyes</i>	1st
Kenneth F. Markgraf	BN	Henry G. Keyes	DIV
0324		0329	
TYPE FULL NAME	TIME OF ARRIVAL	TYPE FULL NAME	TIME OF ARRIVAL

ADMINISTRATIVE COMPANY

REPORT— ADDITIONAL DATA**STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY**

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		IGNITION				STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION				
MONTH	DAY	YEAR	HOUR	MINUTE	SECOND	BOX NO.	BUILDING NO.	FLOOR INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	CONSTRUCTION	USE	STATUS	BOILER DAMAGE	CONTENTS DAMAGED	FLOOR CODE	INITIAL CODE	OCCUPANCY	MANNER OF OCCUPANCY
6	06	25	86	0320	1	0084														

NUMBER (INCL. HYPHEN)		STREET NAME		TYPE		IF MOBILE PROPERTY	
YR.	MAKE	MODEL	79 SERIAL NO.	LICENSE	STATE	ITEM	

UNIT	PTS.	195	201	207	213	219	225	231	236
189									

OPERATIONS**Injury to Members:**

Lt. Ahearn, Lad. 131 Sprain Back

Medical Leave by M.C. Robinson
 Lt. Herrmann, Eng. 9 Sprain left shoulder
 Medical Leave by M.C. Salerno

Chief Officers at Scene:

D.A.C. Fusco,	City Wide Command Chief
D.C. Keyes,	Division 1
B.C. Turner,	Batt. 2
B.C. Hirschfield,	Batt. 4
B.C. Fowler,	Saf. Batt.
M.C. Robinson,	Bur. of Health Ser.

Others at Scene:

Sgt. DiLorenzo,	Port Auth. Police
Sgt. Hetherington,	N.Y.P.D.
Elio Cettina,	Gen. Supt., Fishman Const. Corp.
F.M. Foley,	Bur. of Fire Invest.

B.C. <i>Kenneth P. Markgraf</i> 1st	D.C. <i>Henry G. Keyes</i> 1st	PAGE 1 OF 5
Kenneth P. Markgraf	Henry G. Keyes	
0324	0329	
TYPE FULL NAME	TIME OF ARRIVAL	TIME OF ARRIVAL

ADMINISTRATIVE COMPANY