

FEB 15 '00 16:47 FR AMBASSADOR CONSTR. CO212 949 9762 TO 6693640
FEB. 15. 2000 4:30PM X 212SWANKE HAYDEN CONNELL ARCHT. ENGRS. PC

P.03/04

COSENTINI ASSOCIATES • TWO PENN. PLAZA, NEW YORK, NY 10121 • 212-615-3600 • FAX 212-615-3700

PROJECT MEMORANDUM

TO: Mr. J. Majla - SHCA
FROM: Mr. V. Lemeshev
CC:
SUBJECT: OEM - 7 WTC
JOB NO.: 1854
DATE: February 15, 2000

To improve operating conditions of the fuel oil fill pump set transferring oil from the building storage tank to the tenant's storage tank, as it is based on the field observation by the equipment manufacturer's representative, we recommend to remove existing anti-siphon valve and to install check valve.

Check valve shall be installed as close as possible to the building's storage tank. Use spring loaded check valve for horizontal application.

X:\WPFILES\1834\00\VLJM0215MUI.doc