

08/05/1998 12:31

5165490839

PRECISION INTERIORS

PAGE 02

AMBASSADOR CONSTRUCTION COMPANY, INC.

317 MADISON AVENUE, NEW YORK, N.Y. 10017 TEL. (212) 922-1020 FAX: (212) 949-9782

ESTIMATEDATE 8/4/98SUB-CONTRACTOR Precision Interiors

PROJECT

MAJOR OFFICE -TRADE Drywall

LOCATION

2 W TPHONE NO. 576 5490211CenterSUBS ESTIMATOR JOE LAQUINTO

FLOOR

23 FlESTIMATED FOR MARTY

ARCHITECT DWG. NO.

LATEST DATE

WORK INCLUDED:

5700. Revised work as per Bulletin #1
~~10' Bolt Resistant Anchors~~ ADD ~~6500~~ 5700
Duck open @ 13' DIS add'l labor & framing ADD 5600
(Add wall for 015 - OUT -) ADD 3780 1390
 OK. Patch Column ADD 3500
14 LF DIS PARTITION ADD 2400
ADD EXTRA LAYER ROCK TO HURRICAN WALL ADD 4300
200 LF. 5/8 GYB
CRACK FOR NOT RUNNING WALL TO 5'10" X 2 ADD 14,000

TOTAL PRICE

+19,000

WORK NOT INCLUDED OR ALTERNATES:

Adjusted Price of 51,750 of ORIGINAL P.O.
Add to Above

REMARKS: