

08/05/1998 12:31

5165490839

PRECISION INTERIORS

PAGE 02

AMBASSADOR CONSTRUCTION COMPANY, INC.

317 MADISON AVENUE, NEW YORK, N.Y. 10017 TEL. (212) 922-1020 FAX: (212) 949-9762

ESTIMATE

DATE 8/6/98

SUB-CONTRACTOR Precision Interiors

PROJECT

MAPR OFFICE -

TRADE Drywall

LOCATION

2 W T

PHONE NO. 576 5490211

Center

SUBS ESTIMATOR JOE LAQUINTO

FLOOR

23 Fl

ESTIMATED FOR MARTY

ARCHITECT DWG. NO.

LATEST DATE

WORK INCLUDED:

Revised work AS PER Bulletin #1

To Ball Resistor Add Dry

Duck open @ 13-013 add'l labor & framing

(Add wall Run 45' - out -

Patch Column 22

add 44 LF DIS @ PARTITION 575

add EXTRA LAYER ROCK TO HURICAN WALL

200 LF. 5/8 GYB

CRACK Run Not Running wall to 510x2

<14,000>

+19,000

TOTAL PRICE

WORK NOT INCLUDED OR ALTERNATES:

Agreed Price of \$1,750 of ORIGINAL P.O.

Add to Above

REMARKS: