

08/20/98 14:49 FAX 212 615 3700
08/20/98 THU 13:36 FAX 212 615 3700

SWANKE HAYDEN CONNELL
COSENTINI ASSOCIATES LLP

002/002
002

COSENTINI ASSOCIATES LLP ■ TWO PENN. PLAZA, NEW YORK, NY 10121 ■ 212-615-3600 ■ FAX 212-615-3700

JOB MEMORANDUM

TO: Mr. J. Majia
FROM: Mr. V. Lemeshev
CC: Mr. Michael Maybaum

SUBJECT: OEM
RFI N° 19, 20 21 & 22

JOB NO: 1854

DATE: August 20, 1998

The following is the response to the above mentioned RFI's.

RFI N° 19

As it was confirmed by Mr. M. Schneider of Ambassador Construction, this question is related to the dampers installed at the protective wall and identified as "HD."

These dampers are not part of the smoke control or smoke evacuation system and does not require status indication unless otherwise requested by the user.

Please disregard respective section from our response to RFI N° 13.

RFI N° 20

As per the latest request from the user, base price for the "IID" dampers shall be based on manual dampers at the exterior protective wall and motorized dampers at the interior protective wall.

An add alternate will be based on all "IID" dampers to be electrically operated.

Dampers shall be controlled from the single switch.

Our drawings will be revised accordingly and reissued.

RFI N° 21

No. Proceed as per plans and specs.

RFI N° 22

To follow.

X:\WPFILES\1854.98\VLIK0819 MEM