

Pb JB review 11/6/01

22470, 22471, 22472, 22542, 22543 post ILC failed 3x
22547, post QC failed

22552 reported ~~as~~ 2.252 as 2.2 not 2.3

Rerunning lots of QC until passes 9/18/01 Pb

23083 - 2 samples later - tech problem - affecting result?

9/24/01 Splices causing reruns

Stop avoiding dups of our samples -

9/28/01 Run QC failed right after calibration.
Passed on retry
No sheet for 23321, 2, 3, 4, 5 + 6

What is rerun QC policy?

One replicate may not be enough

10/01/01 Run 1st ILC fails Rerun 23321, 23322, 232425, 26
↳ rerun of ILC passed
Rest of run good.

There are no comments for metals
! 10/1/01 Didn't report results for 23720, 21, 22 + Others ^{14 total}

10/5/01
5:20PM

Reject 23947, 948, 24046, 24047 !
Not surrounded by acceptable Qc

10/9/01

24048, 49, 50, 51, 52, & 24214 Not reported
Rerunning to pass
Spikes failing.

10/9/01 PM

Not reported 23683 - 23692
Reject 23689, 23690, 23691, 23692