



ASBESTOS ANALYTICAL REPORT

ASBESTOS CONTROL PROGRAM LABORATORY
96-05 HORACE HARDING EXPRESSWAY
CORONA, NEW YORK 11368
(718) 595-6309 FAX# (718) 595-6307

ELAP # 11045

TEST METHODS: 1) 40 CFR Part 763, Subpart F, App. A
2) Polarized Light Microscopy plus Stratified Point-Counting Method
3) EPA/600/R-93/116

Incident #: WTC071302
 Inspector : C. LUTCHMEDIAL
 Premise : 15 JOHN STREET
 Boro : Manhattan
 Analyst : L. ATTELONEY

Date Collected: 07/13/02
 Received: 07/13/02
 Analyzed: 07/13/02

Client #:

DEP Sample #:	20713/A058009	20713/A058010	20713/A058011
Laboratory #:	20713/646	20713/647	20713/648
Location Sampled:	WINDOW LEDGE	WINDOW LEDGE	WESTSIDE LOUVER
Color:	GREY	GREY	GREY
Homogenous:	Yes	Yes	Yes
Asbestos Present:	Yes	Yes	Yes

Results (%)

Chrysotile	3.8	Chrysotile	TRACE	Chrysotile	1.2
Cellulose	20	Cellulose	25	Cellulose	30
Fibrous glass	40	Fibrous glass	45	Fibrous glass	45
Matrix	26.2	Matrix	30	Calcites	23.8

Comments:

Reviewed by: *L. Atteloney*
 Laboratory Director

This test report may not be reproduced except with the written approval of this laboratory. The test report relates only to the item(s) listed and does not represent a product endorsement by NVLAP or any other U.S. Government agency.