



March 18, 2002.

Mr. R. Radhakrishnan, P.E.
Director of Asbestos Control Program
NYC Department of Environmental Protection
59-17 Junction Boulevard
Corona, New York 11368-5107

re: 56 Warren Street Owners Corp.
56 Warren Street
New York, New York 10007

Dear Mr. Radhakrishnan;

As per our conversation, please be advised that 56 Warren Street is a residential loft building consisting of 8 residential units and two retail units, as further our conversation the building does not have any central A/C system. The collapse of the World Trade Center caused little damage to the building other than the need to clean the premises. We were advised by our insurance carrier to contact Maxons Restoration for interior cleaning, which they did using Hepa vacuums. The front and rear exterior facades are scheduled to be cleaned by Remco sometime within the next several weeks.

Sincerely,

A handwritten signature in black ink, appearing to read 'Leonard Fox', is written over the typed name.

Leonard Fox, managing agent

ENTERED