


To : P. Theodorellys
From : S. VanderWoude
Org. : NYCDEP

Dear Ms. Theodorellys,

Thanks for the Memo, as per our conversation of Tuesday-11/27/01. Here are the
bulk sample results from Apartments PII at 84 West Broadway.

Sincerely,


Steve VanderWoude

A.K.A

68 Warren St

N8V-28-2001 16:39

P.02

**SCIENTIFIC LABORATORIES, INC.**

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Applied Technology Services, Inc.
Attn: Sieve Vanderwoude
240 North Avenue
New Rochelle, NY 10801

Date Received 10/10/2001 SciLab Job No. 201101939
Date Examined 10/11/2001 P.O. # A01178
ELAP Number 11480 Page 1 of 1
RE: A01178

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
16-101001-11	201101939-01	Yes	<1. %
DUS-002	Location: PII Guest Room Window Track/ In Window Well		

Description: Grey, Heterogeneous, Dust

Asbestos Types: Chrysotile <1. %

Other Material: Cellulose 5. %, Fibrous glass 25. %, Synthetic fibers Trace.
Non-fibrous >69. %

Reporting Notes:

- (1) Composite analysis results for heterogeneous debris samples may be highly variable due to inhomogeneities in materials present

Analyzed by: Jonathan Tede

*NAD/NSD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200546-0) and ELAP PLM Analysis Protocol 198.1 for New York samples (NYSDOH ELAP Lab # 11480). Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested. A11A17 102843; VT Cert# A1.016055

Reviewed By: Paul Hesse

NOV-28-2001 16:40

P.03

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-8382

PLM Bulk Asbestos ReportApplied Technology Services, Inc.
Attn: Steve Vanderwoude
240 North Avenue
New Rochelle, NY 10801

Date Received	10/10/2001	SciLab Job No.	201101945
Date Examined	10/11/2001	P.O. #	A01177
ELAP Number	11480	Page	1 of 1
RE:	A01177		

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
16-101001-07	201101945-01	Yes	<1.0%

Location: White Gray Ash Liv Rm/ South Window Middle - Outside

Description: Grey, Heterogeneous, Dust

Asbestos Types: Chrysotile <1. %

Other Material: Cellulose 8. %, Fibrous glass 25. %, Synthetic fibers Trace,
Non-fibrous >66. %**Reporting Notes:**

- (1) Composite analysis results for heterogenous debris samples may be highly variable due to inhomogenities in materials present

Analyzed by: Jonathan Teda

Jonathan Teda by Belle Cui

*NAD/NSD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200546-0) and ELAP PLM Analysis Protocol 198.1 for New York samples (NYSDOH ELAP Lab # 11480); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested. AIHA# 102843; VT Cert# AL016055

Reviewed By:

Lance Teda

