

**49 Murray House Condominium Association
49 Murray Street
New York, N.Y.
10007**

Department of Environmental Protection
R. Radhakrishnan, Director Asbestos Control Program
59-17 Junction Boulevard
Corona, New York
11368-5107

March 5, 2002

RE: 49 Murray St. New York, New York

Dear Mr. Radhakrishnan,

We received your letter dated February 12 on February 28 by facsimile transmission.

On September 29, 2001 we negotiated with ServPro/ PRO Restoration Cleaners and our insurance company to have the interior of 49 Murray Street cleaned to remove the dust and dirt created by the events of September 11, 2001.

In addition to ServPro, we hired Knightaire HVAC Inc. to clean the air conditioning ducts and replace the a/c filters.

We did not do any additional air monitoring. Some of the residents have purchased heppa air purifiers that they operate in their homes 24 hours a day.

If there is more information that you require, please don't hesitate to call me at 304-478-1046 or fax at 304-478-1097.

Thank you,



Robin Nemlich McClintock
H.C. 66 Box 10A
Hendricks, West Virginia 26271