

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail

Report Date 02/21/2002 09:50 AM

Submitted By

Page 1

Service # 409878

Problem BWTC ASBESTOS: WTC (USE COMMENTS)

Address 74 TRINITY PL 1

10006

Cross Streets RECTOR ST

THAMES ST

Compass Direction

Building ID 10010

Block 00051

Lot 0017

CMDB 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 02/12/2002 12:03

Taken By 7213

MURPHY, LEROY

Responsibility BHZ

BANHAZMAT (AIR,NOISE,HAZ.MAT)

Priority

Scheduled Date

Inspector

Due Date

Asset

Avg Insp Duration

Customer Contact Req

Budget #

Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

COMPLETED

Problem Comments

Initial Caller

Last Name KERNER

Title MS

First Name, MI KEN

Address

SUITE 1402

City, State/Province, ZIP/PC

Foreign

Day Phone (212)964-1098 x

Evening Phone

Call Date 02/12/2002 12:03

Reference #

Caller Comments

AIR THAT NEEDS TO BE TESTED, PLS INVESTIGATE///CALL TO SET APPT ASK FOR KEN KURNER (2-19-02)

Inspected				Resolution			
By	Date	Time	Code	Date	Time	Code	
CARL	2/14/02	4:30p	5	2/14/02	5:00		

Met Ken Kerner, he said that he wanted an office tested. They believe that the office was not properly cleaned. I did not observe any WTC dust in office.