

250 SOUTH END AVE. AKA
~~CATTARAUGUS PLAZA~~

Address: _____

Bulk Samples
 PLM

Yes

No

Number of Negative ($\leq 1\%$) Samples

5

Number of Positive ($> 1\%$) Samples

1

ALSO PERFORMED VIA TEM 5 SAMPLES: 3 NEGATIVE, 2 POSITIVE
 (DID NOT PROVIDE CONCENT. CRITERIA E.G. $> 10\%$) FOR 9-28-01
 SAMPLES. THE NUMS ABOVE DID NOT INDICATE IF BULK. ALSO DID
 A TEM ON ONE 11-14-01 DUST SAMPLE;
 RESULT WAS 1.2% ASB. FIBERS

Air Samples

Yes

No

PCM

Number of Samples Collected (≤ 0.01 f/cc)

4

Number of Samples Collected (> 0.01 f/cc)

TEM

Number of Samples Collected (≤ 70 s/mm²)

36

Number of Samples Collected (> 70 s/mm²)

ALSO DID A TEM ON ONE 11-14-01 SAMPLE: RESULT
 WAS < 0.01 f/cc

LAB REPORT FOR ALL ABOVE NOT
 PROVIDED

ALSO INDICATED THAT CLEANING DONE

Bm

RY Management Co. Inc.

1619 Third Avenue
New York, NY 10128
Phone: (212) 534-7771
Fax: (212) 534-2944

Fax

To: R. RADHAKRISHNAN, PE. From: John Piastra
Fax: 718-595-3744 Date: 02/19/02
Phone: _____ Pages: 16
Re: HUDSON VIEW EAST CONDO. CC: _____
☐ Urgent ☐ Please Comment ☐ Please Reply
DT LAWYER 188
•Comments: _____

If any problems should occur with this transmission, please call (212) 534-7771.

PT.

Address: HUDSON VIEW EAST CONDO

Bulk Samples
PLM

Yes

No

Number of Negative ($\leq 1\%$) Samples _____

Number of Positive ($> 1\%$) Samples _____

Air Samples

Yes

No

PCM

Number of Samples Collected (≤ 0.01 f/cc) _____

Number of Samples Collected (>0.01 f/cc) _____

TEM

Number of Samples Collected (≤ 70 s/mm²) _____

Number of Samples Collected (>70 s/mm²) _____