

Hello Effie,

Claimants: Kristen Hart & Luis Rodriquez.

Is the below and attached information from James Garin sufficient? You had requested that I obtain information as to why water mains were added to the project.

As James indicated, Nick will forward the scope sketches for the retaining wall project.

Thank you.

Sarah

Sarah Pener, Consent Decree Coordinator/NYC Environmental Protection
0)(718)595-6536(m) PII

From: Garin, James

Sent: Tuesday, May 13, 2014 8:59 AM

To: Pener, Sarah; Brawer, Vivian; Ardizzone, Eleftheria

Cc: Barbaro, Nicholas; Gordon, Peter; Marchesano, Anthony

Subject: FW: Attached Image

Sarah, please see the attached service request report from our Maintenance Division. It shows that we responded to a street cave-in and discovered multiple service line breaks. Usually, an undetected break will wash away the soil in the area that causes a sink hole and the possibility of other breaks. There is no mention of the retaining wall in the report.

Nick, will forward to you the scope sketches for the retaining wall project. The water main replacements are added to capital projects based on age requirements. All water mains in a Capital Contract today get replaced if they were installed prior to 1970. Thanks

From: Fanouse, Amil

Sent: Tuesday, May 13, 2014 8:32 AM

To: Garin, James

Subject: FW: Attached Image

FYI

Amil Fanouse, P.E. | Engineer – In – Charge | NYC Environmental Protection
Bureau Of Water & Sewer Operations – Project Development Section
(O) 718 595 5472 | afanouse@dep.nyc.gov

5/13/2014



CSR# 185626249

Service Request Detail Report

Report Date: Tuesday, May 13, 2014

Page 1 of 2

Service# 185626249

Problem: WA2 LEAK (USE COMMENTS)

Address(A): 3488 CANNON PL

APT:

Cross Street: BEND
W 238 ST

ZIP: 10463 Pct: 050

Borough: BRONX

Compass Direction:

SegmentID: 0113567

Building ID: 2015852

Block: 3258

Lot: 186

CMBD: 208

Location:

District:

Parcel:

Area: 2 BRONX

Sub-Area: 208 BRONX COMMUNITY BOARD 8

of Calls: N/A

Occurred Date: N/A

Call Date: 07-30-2013 11:18 AM

Taken By: 7261

GILMORE, MALARIE

Request Date: 07-30-2013 11:18 AM

Responsibility: WMX

WATER MAINTENANCE - BRONX

Source: N/A

Scheduled Date: N/A

Start Date: 07-30-2013 12:45 PM

Priority: U- AFFECTING UTILITY

Inspector: 6825

VOLGARE, LAWRENCE

Inspection Date: 07-30-2013 01:45 PM

Resolution Code: WLRHO

LEAK RESOLVE BY HOME OWNER

Resolution Date: 08-14-2013 09:15 PM

Customer Contact Requested: N

Incident Date: N/A

Due Date: N/A

Primary Caller Information

Title:

Reference#

N/A

CallerKey: 185626249

Last Name: CON EDISON

Evening Phone:

N/A

First Name, MI: BRADDY

Cell Phone:

N/A

Address:

Day Phone:

PII

City/State/Zip:

Call Date: 07-30-2013 11:18 AM

Caller Comments: WATER LEAK IN A CON EDISON EXCAVATION
CON EDISON IS ON LOCATION
718-319-2331-24 HOUR CONTACT NUMBER

Log Type	Log Started	Log Ended	Log By	Comments
ESC311	07-30-2013	N/A	7261-GILMORE, MALARIE	SPOKE WITH FRANK Input By: MALARIE GILMORE on 7/30/2013 11:24:16 AM
INITIAL	07-30-2013	07-30-2013	2187-CURBELO, ROSEMARY	3488 CANNON PL 7-30-13 1245-1345 LANGONE MANNIELLO # 423 UPON ARRIVAL CON ED ALREADY BACKFILLED HOLE BUT TOLD US CLEAN WATER ENTERING EXCAVATION BX 3 WAS 3490 -3488 FOUND BOTH HOUSES WITH BROKEN SEWER LINES .3490 STATED HAS VERY LOW PRESSURE IN THE HOUSE SOUNDED SERVICE LINE BEFORE AND AFTER GOT NOISE SERVED THREE DAY TO 3490 CANNON PL Input By: ROSEMARY CURBELO on 8/1/2013 3:03:17 PM



CSR# 185604360

Service Request Detail Report

Report Date: Tuesday, May 13, 2014

Page 1 of 2

Service# 185604360

Problem: SG1 STREET CAVE-IN *DEP INTERNAL USE ONLY*

Address(A): 3488 CANNON PL

APT:

Cross Street: BEND
W 238 ST

ZIP: 10463 Pct: 050

Borough: BRONX

Compass Direction:

SegmentID: 0113567

Building ID: 2015852

Block: 3258

Lot: 186

CMBO: 208

Location:

District:

Parcel:

Area: 2 BRONX

Sub-Area: 208 BRONX COMMUNITY BOARD 8

of Calls: N/A

Occurred Date: N/A

Call Date: 06-28-2013 11:07 AM

Taken By: 7983

SOBHANI, MARTHA

Request Date: 06-28-2013 11:07 AM

Responsibility: SX

SEWER MAINTENANCE-BRONX

Source: CARS- CARS Issued by DOT/HIQA

Scheduled Date: N/A

Start Date: 06-30-2013 08:30 AM

Priority: Z- DEFAULT PRIORITY

Inspector: 1026

ABRUSCI, JOHN

Inspection Date: 06-30-2013 09:00 AM

Resolution Code: S689

OTHER - SEE REMARKS

Resolution Date: 07-01-2013 09:30 AM

Customer Contact Requested: N

Incident Date: N/A

Due Date: N/A

Primary Caller Information

Title:

Reference#

20134820359

CallerKey: 185604360

Last Name: HIQA

Evening Phone:

N/A

First Name, MI: DOT

Cell Phone:

N/A

Address: 1400 WILLIAMSBRIDGE RD 1ST FLOOR

Day Phone:

(212)748-6611

City/State/Zip: BRONX NEW YORK 10461

Call Date: 06-28-2013 11:07 AM

Caller Comments: CAR NUMBER: 20134820359

DEFECT CODE: 97 Cave-Ins

CAR COMMENT: A 2ft x 1ft cave in down 2ft in the parking lane in front of building # 3488-90.in reference to SR#665065850

PERMIT #: XNP2013482099

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	06-30-2013	06-30-2013	7800-RIVERA, JOSE	3488 CANNON PL 6/30/13 0830-0900 MACCHIA NO-CREW DYED CAVE IN AT CURB SIDE, DYE SHOWED POSITIVE. SPOKE WITH HOMEOWNER OF 3488 INFORMED HIM WE NEED TO TV HIS HOUSE LINE. HIS TRAP IS COVERED WITH DIRT. HE WILL CLEAN IT AND ASKED IF WE CAN RETURN 7/1/13 AT 830AM. ALSO MAY NEED TO TV #3490 & 3488 CANNON PL. Input By: JOSE RIVERA on 7/2/2013 11:17:00 AM
FOLLOWUP	07-01-2013	07-01-2013	7800-RIVERA, JOSE	3488 CANNON PL 7/1/13 0830-0930 MACCHIA PAGNOTTA/ALONZO TV'D HOUSE LINE TO 3488 SHOWED MULTIPLE BREAKS ON HOUSE LINE. INFORMED HOME OWNER TO ENGAGE PLUMBER, ALSO TV 3490 SHOWED MULTIPLE BREAKS ON HOUSE LINE. INFORMED HOMEOWNER TO ENGAGE PLUMBER. BOTH LINES CONFIRMED BROKEN. Input By: JOSE RIVERA on 7/2/2013 11:18:34 AM