

05/05/99 09:34 FAX 2122190256
05/04/99 12:33 FAX 212 736 3519

SWANKE HAYDEN CONNELL
COSENTINI ASSOCIATES

008
002

COSENTINI ASSOCIATES LLP ■ TWO PENN. PLAZA, NEW YORK, NY 10121 ■ 212-615-3600 ■ FAX 212-615-3700

JOB MEMORANDUM

TO: Mr. Joe Aliotta, SHCA **SUBJECT:** FDNY

FROM: Michael W. Maybaum **JOB NO:** 1332

CC: Mr. S. Vaclavik, CA **DATE:** May 4, 1999
Mr. V. Lemeshev, CA

Comment No.	Dwg. No./Spec. Section	Comments	CA Comments
		These drawings are approved subject to the following corrections/clarifications:	
		Mechanical	
1	M-103	► Clarify with a section, the construction detail of the linear diffuser near column C11.	Will comply.
2	M-104	► Provide exhaust fan for the lunch room near Column 11A. ► Add diffuser for the existing pantry near Column 9.5E. ► Show location of thermostat for VAV boxes. ► Correct the air distribution's description for the command console area. ► Verify the need to provide an exhaust fan for the battery back up room.	Will comply. Will comply. Will comply. Will comply. Required.
3	Spec. Section 15140-2	► add acoustical lining requirements downstream of VAV boxes.	Will comply.
4	Spec. Section 15150	► Elaborate on how the automatic switch will operate to change the damper status.	Control system will activate dampers.
		Electrical	
1	E-104	► Indicate the power entry to Herman Miller furniture. ► Indicate the power requirements to the VAV & Cv boxes and exhaust fans.	Herman Miller furniture system is not electrified. Will comply.
2	E-300	► Provide revised UPS drawings.	Will comply.

05/05/99 09:34 FAX 2122190256
05/04/99 12:00 FAX 212 736 3519

SWANKE HAYDEN CONNELL
COSENTINI ASSOCIATES

007
003

COSENTINI ASSOCIATES LLP ■ TWO PENN. PLAZA, NEW YORK, NY 10121 ■ 212-615-3600 ■ FAX 212-615-3700

		Plumbing	
1	P-104	► Indicate the drainage from the preaction system thru indirect waste.	

X:\WPFILES\1332.99\MMHC0504.M01