

**BENJAMIN KURZBAN
& SON CONTROL, INC.**1248 Ralph Ave.
BROOKLYN, N.Y. 11236**INVOICE**

1226

(718) 531-2900

TO Dept of Environmental Protection
59-17 Junction Blvd
Corona, NY 11378

DATE 11/12/02	ORDER NO.
SHIP TO Contract ROF-REM 2	

SALESPERSON	DATE SHIPPED	SHIPPED VIA	F.O.B. POINT	TERMS	
QUANTITY	DESCRIPTION			UNIT PRICE	TOTAL
>	Registration # CT 82620020015280				
	Pin # 82602WTCROOF 2				
	For work completed at 39 John St				
	15,346 SF @ 2/SF				
	Total Amount due this Invoice				\$30,692.00
	R. Raehn				

ORIGINAL

Thank You!


NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program

59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107

ASBESTOS PROJECT NOTIFICATION
(ASBESTOS INSPECTION REPORT)

ONLY
TYPEWRITTEN
FORMS WILL BE
ACCEPTED



1. NYC DEP
(See fee schedule)

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

I. FACILITY

2. Address 39 John St Borough Manhattan Zip 10038
AKA 72-78 Nassau St 3. Block 78 4. Lot 35
5. Type of Facility _____ 6. Name of Building _____

II. BUILDING OWNER

7. Name GALB- REALTY ASSOCIATES 8. Contact Person CHARLES GANGLER
9. Tel. # _____ Fax # _____
10. Address 113 CEDAR STREET City NEW YORK State NY Zip 10006

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name Benjamin Kurzban & Son Control 13. Contact Person Louie Iannico
14. Federal Employer ID. # PII 15. Tel. # (718) 531-2900 Fax # (718) 209-1808
16. Address 1248 Ralph Avenue City Brooklyn State NY Zip 11236

V. THIRD PARTY AIR MONITOR

17. Name Warren & Panzer ENGINEERS 18. Contact Person MICHAEL NOLAN
19. Federal Employer ID. # PII 20. Tel. # (212) 922-0077 Fax # (212) 922-0630
21. Address 228 East 45th St City New York State NY Zip 10017
22. Sample Analysis Laboratory _____ 23. NYS DOH ELAP # _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work 11/04/02 Projected completion date 11/30/02

Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday


Shift from: 7⁰⁰ ☒ am ☐ pm to 7⁰⁰ ☐ am ☒ pm

If other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

15346 Square Feet, and/or 0 Linear Feet



ACP 7
2/2001

39 JOHN ST

ASBESTOS INSPECTION REPORT (continued)26. Asbestos Hauler IESI, NY NYS DEC Permit # NJ-462 Tel.# (718) 522-2263Disposal Site(s) BlueRidge Landfill PO Box 399 Scotsdale, Pa 17254

27. This asbestos abatement is part of a (Item a through e requires filing of this form with NYC Department of Buildings)

- a) ☐ Demolition b) ☐ Boiler Replacement c) ☐ Sprinkler Replacement d) ☐ Renovation/Alteration
 e) ☐ Fireproofing Replacement f) ☒ Other (Describe) _____

28. TYPE OF ABATEMENT (Check all appropriate boxes)

- ☐ Removal ☐ Enclosure ☐ Encapsulation ☐ Repair ☒ Clean up



29. ABATEMENT PROCEDURE (Check all appropriate boxes)

- ☐ Full Containment ☐ Glovebag ☐ Tent ☐ DEP Variance Application


30. LOCATIONS OF ABATEMENT

Floor(s)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc.)	AFFECTED SURFACES CONTAINING ACM (e.g. Pipe lagging, ceiling, plenum ducts, storage tanks, decking, etc.)	AMOUNT OF ACM SQUARE FEET LINEAR FEET		DESCRIPTION OF WORK BEING PERFORMED (e.g. running cable, installing fire sprinklers, removing and replacing boilers, etc.)
FACADE	WEST	FACADE SURFACE	5200		
"	SOUTH	" "	4000		
"		AWNINGS / SIGNS	2000		
"		STORE FRONTS	1840		
"	NORTH	FACADE SURFACE	600		
"	EAST	" "	750		
SET BACK		ROOF SURFACE	456		
		METAL / FWE	500		

31. I hereby declare that the information provided herein is true and complete to the best of my knowledge. I am familiar with Federal, State and NYC laws and regulations applicable to asbestos related work.

WARREN & PANZER ENGINEERS Print Name of Air Monitor  Signature <u>10/30/02</u> Date	B. KURZBAN & SON CONTROL Print Name of Asbestos Contractor  Signature <u>10/30/02</u> Date	_____ Print Name of Applicant (If other than Owner) _____ Signature _____ Date
--	---	---

32. I understand that as the owner of a building where asbestos abatement activity occurs, I am responsible for the performance of the asbestos abatement activities in accordance with the Asbestos Control Program Rules. I have contracted the third party air monitor who is completely independent of all parties involved in the asbestos project. I hereby declare that I have authorized the filing of this notification for the work specified herein.

 Print Name of Owner  Signature 10/30/02 Date

A STAMPED COPY OF THIS FORM INCLUDING AMENDMENTS MUST BE AVAILABLE AT THE WORK SITE.

Any modification of information provided on this form must be reported immediately in writing directly to the NYC DEP ACP.

The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.

ACP7
2/2001



AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warren & Panzer Engineers, P.C.
LABORATORY ID #: T02-11-021
ANALYT. METHODOLOGY: AHERA
FILTER TYPE: M.C.B.
AVERAGE G.O. AREA (mm²): 0.013433

PROJECT: NYC DEP, 39 John Street
DATE OF REPORT: 11/05/02
DATE OF ANALYSIS: 11/05/02
EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (M)	G.O. ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIV. (struct./cm ²)	TOTAL ASBESTOS AIR CONC. (struct./cm ³)	TOTAL ASBESTOS FILTER CONC. (air./mm ²)	AIR CONC. FOR STRUCT. 0.5 ≤ S ≤ 5 μm	AIR CONC. FOR STRUCT. S ≥ 5.0 μm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-11-021-3780	Inside work area south	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
02	T02-11-021-3781	Inside work area east	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
03	T02-11-021-3782	Inside work area west	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
04	T02-11-021-3783	Inside work area center	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
05	T02-11-021-3784	Inside work area north	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA

ANALYST
E. Dimitrakas

LABORATORY DIRECTOR
Spiro Dongaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101938, BLAP 10935

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

Dec 31, 00 16:13 No.003 P.04



AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warren & Panzer Engineers, P.C.
LABORATORY ID #: T02-11-050
ANALYT. METHODOLOGY: AHERA
FILTER TYPE: M.C.E.
AVERAGE G.O. AREA (mm²): 0.013433

PROJECT: NYC DEP, 39 John Street
DATE OF REPORT: 11/10/02
DATE OF ANALYSIS: 11/10/02
EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (L)	G.O.'s ANAL YZED	AREA ANALY ZED (mm ²)	ANALYT. SENSITV. (struc./cm ²)	TOTAL ASBESTOS AIR CONC. (struc./cm ³)	TOTAL ASBESTOS FILTER CONC. (str./mm ²)	AIR CONC. FOR STRUCT. 0.5<S<5µm	AIR CONC. FOR STRUCT. 5<S<10µm	ASBEST. TYPE CHRS.	AMPHIB. ASBEST TYPE SPECIFY
01	T02-11-050-3954	South side of façade	1800	4	0.0537	0.0040	<0.0040	<18.61	NA	NA	NA	NA
02	T02-11-050-3955	Middle of façade 1	1800	4	0.0537	0.0040	<0.0040	<18.61	NA	NA	NA	NA
03	T02-11-050-3956	Middle of façade 2	1800	4	0.0537	0.0040	<0.0040	<18.61	NA	NA	NA	NA
04	T02-11-050-3957	Middle of façade 3	1800	4	0.0537	0.0040	<0.0040	<18.61	NA	NA	NA	NA
05	T02-11-050-3958	North side of facade	1800	4	0.0537	0.0040	<0.0040	<18.61	NA	NA	NA	NA

ANALYST
E. Sioukri

LABORATORY DIRECTOR
Spiro Dongaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE ____ OF ____

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate⁺/a

P.O. _____

225 West 45th Street
 New York, NY 10017
 (212) 922-0077
 Fax (212) 922-0630

CLIENT: NYC DEP
 PROJECT: FACADE
 LOCATION: 39 JOHN

W&P FILE #: 1079-02-01
 LABORATORY: HTHENICA
 ANALYSIS METHOD: PCM TEM TEM
circle one 7400 AHERA EPA LEVEL II
 TECHNICIAN: FESTI BERNIERE

CONTACT: _____

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE		TIME		TOTAL TIME	VOLUME (liters)	CONCENTR. (lb./cc.)
				START	STOP	ON	OFF			
01	SOUTH SIDE OF FACADE	3		4	4	0900	1630	450	1800	
02	MIDDLE OF FACADE 1	3		4	4	0902	1632	450	1800	
03	" " " 2	3		4	4	0904	1634	450	1800	
04	" " " 3	3		4	4	0906	1636	450	1800	
05	NORTH SIDE OF FACADE	3		4	4	0908	1638	450	1800	
06	BLANK	1	---							
07	"	1	---							

COMMENTS:

T02-11-050

SAMPLE BY: <u>FESTI BERNIERE</u>	DATE: <u>11-09-02</u>
SIGNATURE: <u>[Signature]</u>	
RELEASED BY: <u>FESTI BERNIERE</u>	DATE: <u>11-09-02</u>
SIGNATURE: _____	
RECEIVED BY: <u>ACATIGAL</u>	DATE: <u>11/11/02</u>
SIGNATURE: <u>[Signature]</u>	

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

Dec 31,00 15:13 No.003 P.05 11/10/2002 10:24 FAX

Asbestos Inspection Report

Premise No. 72-78 NASSAU STREET AKA 37-39 JOHN STREET					Inspection Date: AS NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 78	Lot 35	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken ☒ Yes ☐ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: As NOTED		

MONDAY NOVEMBER 4 2002

THE CLEAN UP OF THE EAST FACADE AND METAL WORK ON THE ROOF OF THE PREMISE BEGAN. WORKERS WORE DOUBLE PROTECTIVE SUITS AND UTILIZED STEP OFF PADS. NO DECONTAMINATION UNIT WAS ERECTED. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY CELESTINE NMORKA (CERTIFICATE # AH 0208495 EXP 04/03)

TUESDAY NOVEMBER 5 2002

THE CLEAN UP OF THE EAST FACADE AND THE METAL WORK ON THE ROOF WAS COMPLETED. THE CLEAN UP OF THE SOUTH AND WEST FACADES IS SCHEDULED FOR NOVEMBER 9-10 2002.

WEDNESDAY NOVEMBER 6 2002

I CONDUCT A VISUAL INSPECTION OF THE CLEANED SURFACES AND ORDERED A MINOR RE CLEANING OF SOME METAL WORK ON THE ROOF. AT THE CONCLUSION OF THE RE CLEANING ACTIVITIES, I RE-INSPECTED THE METAL WORK AND I OBSERVED NO VISIBLE WTC DEBRIS. NO VISIBLE DEBRIS WAS OBSERVED ON THE EAST FACADE SURFACES.

SATURDAY NOVEMBER 9 2002

THE CLEAN UP OF THE WEST FACADE (NASSAU STREET SIDE) WAS CONDUCTED TODAY.

600 AM: WORKERS ARRIVE AT THE JOBSITE

630 AM: CONSTRUCTION OF PLASTIC DYKE (TO COLLECT RUN OFF WATER) BEGINS.

800 AM: CONSTRUCTION OF DYKE COMPLETED. PLASTICIZING OF STORE FRONTS BEGINS

900 AM: STORE FRONTS HAVE BEEN PLASTICIZED. AIR SAMPLING BEGINS. AIR SAMPLING EQUIPMENT IS SET UP ON THE OPPOSITE SIDEWALK. AIR SAMPLING IS PERFORMED BY FESZY OSEMIWEGIE (CERTIFICATE # AH 01-01030 EXP 01/03) OF WARREN & PANZER ENGINEERS

VACUUMING OF BULK DEBRIS FROM WINDOW LEDGES BEGINS. A DECONTAMINATION TRUCK IS UTILIZED FOR WORKER DECONTAMINATION.

Asbestos Inspection Report

Premise No. 72-78 NASSAU STREET AKA 37-39 JOHN STREET	Inspection Date: AS NOTED
Inspector Dennis Antzoulatos	Page <u>2</u> of <u>2</u>

SATURDAY NOVEMBER 9 2002 (CONTINUED)

1130 AM: VACUUMING OF BULK DEBRIS HAS BEEN COMPLETED. WORKERS BREAK FOR LUNCH.

1230 PM: POWER WASHING OF THE FACADE SURFACES BEGINS.

0400 PM: POWER WASHING ACTIVITIES ARE COMPLETED.

0400PM-0430 PM: I CONDUCT A VISUAL INSPECTION OF THE CLEANED FACADE SURFACES.
RECLEANING IS REQUIRED BEHIND THE "NEXTEL" AND "ELITE" STORE SIGNS

0430 PM: AIR SAMPLING IS COMPLETED.

0500 PM: RE CLEANING BEHIND THE TWO SIGNS HAS BEEN COMPLETED.

0500PM-0530PM: DYKE IS DISMANTLED. PLASTIC USED FOR DYKE IS BAGGED.

0530 PM: WASHING OF SIDEWALK AND STREET BEGINS.

0600 PM: SIDEWALK AND STREET CLEAN UP HAS BEEN COMPLETED.

SUNDAY NOVEMBER 10 2002

THE CLEAN UP OF THE SOUTH FACADE (JOHN STREET) WAS CONDUCTED TODAY

0600AM: WORKERS ARRIVE AT THE JOB SITE

0700AM: ENTRANCE TO SUBWAY AT THE CORNER OF JOHN ST AND NASSAU ST IS COVERED WITH PLASTIC SHEETING.

0730AM: CONSTRUCTION OF PLASTIC DYKE BEGINS.

0900 AM: AIR SAMPLING EQUIPMENT IS SET UP ON THE OPPOSITE SIDEWALK. AIR SAMPLING IS PERFORMED BY FESLY OSMWEGIE OF WARREN & PANZER ENGINEERS

0935 AM: AIR SAMPLING BEGINS. VACUUMING OF BULK DEBRIS FROM WINDOW LEDGES BEGINS.

1100AM: VACUUMING OF BULK DEBRIS HAS BEEN COMPLETED. POWER WASHING ACTIVITIES BEGIN

1200PM-0100 PM: WORKERS BREAK FOR LUNCH.

0500PM: POWER WASHING ACTIVITIES ARE COMPLETED.

0500PM-0530 PM: I CONDUCT A VISUAL INSPECTION OF THE CLEANED FACADE SURFACES. MINOR RECLEANING IS REQUIRED ON THE AWNINGS AND ROLL DOWN GATES.

0600PM: ROLL DOWN GATES HAVE BEEN CLEANED. AWNINGS WILL BE VACUUMED WHEN DYKE DISMANTLING OF PLASTIC DYKE BEGINS.

0630 PM: DYKE HAS BEEN DISMANTLED AND PLASTIC SHEETING HAS BEEN BAGGED. WASHING OF SIDEWALK AND STREET BEGINS

0700PM: SIDEWALK AND STREET CLEAN UP HAS BEEN COMPLETED.

MONDAY NOVEMBER 11 2002

THE CLEANING OF STORE FRONT WINDOWS BEHIND THE METAL ROLL DOWN GATES WAS CONDUCTED TODAY. AT THE CONCLUSION OF THE CLEANING ACTIVITIES, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND I OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT AT THE PREMISE IS NOW COMPLETE.



AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warren & Panzer Engineers, P.C.
LABORATORY ID #: T02-11-053
ANALYT. METHODOLOGY: AHERA
FILTER TYPE: M.C.E.
AVERAGE G.O. AREA (mm²): 0.013433

PROJECT: NYC DEP, 39 John Street
DATE OF REPORT: 11/11/02
DATE OF ANALYSIS: 11/11/02
EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (M)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIV. (str./cm ²)	TOTAL ASBESTOS AIR CONC. (str./cm ³)	TOTAL ASBESTOS FILTER CONC. (str./cm ²)	AIR CONC. FOR STRUCT. 0.5 < S < 5 µm	AIR CONC. FOR STRUCT. S > 5 µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-11-053-3970	West side of façade	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
02	T02-11-053-3971	Middle of façade #1	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
03	T02-11-053-3972	Middle of façade #2	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
04	T02-11-053-3973	Middle of façade #3	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
05	T02-11-053-3974	East side of façade	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA

ANALYST
E. Dimitrakas

LABORATORY DIRECTOR
Spiro Dongaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

TEL:

Jan 03, 01

8:15 No. 001 P. 03

228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE OF _____

P.O. _____

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ⁺/a

CLIENT: NYC DEP
PROJECT: FACADE
LOCATION: 39 JOHN ST

W&P FILE #: 1078-02-01
LABORATORY: ATHEMCA
ANALYSIS METHOD: PCM TEM TEM
circle one 7400 ATHEMCA EPA LEVEL II
TECHNICIAN: Fegit Chen

CONTACT: _____

[illegible]

COMMENTS:

SAMPLE BY: FERTY OSENBERG DATE: 11-10-02
SIGNATURE: [Signature]
RELEASED BY: FERTY O. DATE: 11-10-02
SIGNATURE: _____
RECEIVED BY: A. CAJIGA DATE: 11/11/02
SIGNATURE: [Signature]

702-11-053

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

TEL:

Jan 03, 01

8:15 No. 001 P. 02