

Asbestos Inspection Report

Premise No. 72-78 NASSAU STREET AKA 37-39 JOHN STREET					Inspection Date: AS NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 78	Lot 35	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken (Yes) No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		

MONDAY NOVEMBER 4 2002

THE CLEAN UP OF THE EAST FACADE AND METAL WORK ON THE ROOF OF THE PREMISE BEGAN. WORKERS WORE DOUBLE PROTECTIVE SUITS AND UTILIZED STEP OFF PADS. NO DECONTAMINATION UNIT WAS ERECTED. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY CELESTINE NMORKA (CERTIFICATE # AH 0208495 EXP 04/03)

TUESDAY NOVEMBER 5 2002

THE CLEAN UP OF THE EAST FACADE AND THE METAL WORK ON THE ROOF WAS COMPLETED. THE CLEAN UP OF THE SOUTH AND WEST FACADES IS SCHEDULED FOR NOVEMBER 9-10 2002.

WEDNESDAY NOVEMBER 6 2002

I CONDUCT A VISUAL INSPECTION OF THE CLEANED SURFACES AND ORDERED A MINOR RE-CLEANING OF SOME METAL WORK ON THE ROOF. AT THE CONCLUSION OF THE RE-CLEANING ACTIVITIES, I RE-INSPECTED THE METAL WORK AND I OBSERVED NO VISIBLE WTC DEBRIS. NO VISIBLE DEBRIS WAS OBSERVED ON THE EAST FACADE SURFACES.

SATURDAY NOVEMBER 9 2002

THE CLEAN UP OF THE WEST FACADE (NASSAU STREET SIDE) WAS CONDUCTED TODAY.

600 AM: WORKERS ARRIVE AT THE JOBSITE

630 AM: CONSTRUCTION OF PLASTIC DYKE (TO COLLECT RUN OFF WATER) BEGINS.

800 AM: CONSTRUCTION OF DYKE COMPLETED. PLASTICIZING OF STORE FRONTS BEGINS

900 AM: STORE FRONTS HAVE BEEN PLASTICIZED. AIR SAMPLING BEGINS. AIR SAMPLING EQUIPMENT IS SET UP ON THE OPPOSITE SIDEWALK. AIR SAMPLING IS PERFORMED BY FESTY OSEMWEIGIE (CERTIFICATE # AH 01-01030 EXP 01/03) OF WARREN & PANZER ENGINEERS

VACUUMING OF BULK DEBRIS FROM WINDOW LEDGES BEGINS. A DECONTAMINATION TRUCK IS UTILIZED FOR WORKER DECONTAMINATION.

Asbestos Inspection Report

Premise No. 72-78 NASSAU STREET AKA 37-39 JOHN STREET	Inspection Date: AS NOTED
Inspector Dennis Antzoulatos	Page <u>2</u> of <u>2</u>

SATURDAY NOVEMBER 9 2002 (CONTINUED)

1130 AM: VACUUMING OF BULK DEBRIS HAS BEEN COMPLETED. WORKERS BREAK FOR LUNCH.

1230 PM: POWER WASHING OF THE FACADE SURFACES BEGINS.

0400 PM: POWER WASHING ACTIVITIES ARE COMPLETED.

0400PM-0430 PM: I CONDUCT A VISUAL INSPECTION OF THE CLEANED FACADE SURFACES.

RECLEANING IS REQUIRED BEHIND THE "NEXTELL" AND "ELITE" STORE SIGNS

0430 PM: AIR SAMPLING IS COMPLETED.

0500PM: RE CLEANING BEHIND THE TWO SIGNS HAS BEEN COMPLETED.

0500PM-0530PM: DYKE IS DISMANTLED. PLASTIC USED FOR DYKE IS BAGGED.

0530 PM: WASHING OF SIDEWALK AND STREET BEGINS.

0600 PM: SIDEWALK AND STREET CLEAN UP HAS BEEN COMPLETED.

SUNDAY NOVEMBER 10 2002

THE CLEAN UP OF THE SOUTH FACADE (JOHN STREET) WAS CONDUCTED TODAY

0600AM: WORKERS ARRIVE AT THE JOB SITE

0700AM: ENTRANCE TO SUBWAY AT THE CORNER OF JOHN ST AND NASSAU ST IS COVERED WITH PLASTIC SHEETING.

0730AM: CONSTRUCTION OF PLASTIC DYKE BEGINS.

0900 AM: AIR SAMPLING EQUIPMENT IS SET UP ON THE OPPOSITE SIDEWALK. AIR SAMPLING IS PERFORMED BY FESLY OSMWEGIE OF WARREN & PANZER ENGINEERS

0935 AM: AIR SAMPLING BEGINS. VACUUMING OF BULK DEBRIS FROM WINDOW LEDGES BEGINS.

1100AM: VACUUMING OF BULK DEBRIS HAS BEEN COMPLETED. POWER WASHING ACTIVITIES BEGIN

1200PM-0100 PM: WORKERS BREAK FOR LUNCH.

0500PM: POWER WASHING ACTIVITIES ARE COMPLETED.

0500PM-0530 PM: I CONDUCT A VISUAL INSPECTION OF THE CLEANED FACADE SURFACES. MINOR RECLEANING IS REQUIRED ON THE AWNINGS AND ROLL DOWN GATES.

0600PM: ROLL DOWN GATES HAVE BEEN CLEANED. AWNINGS WILL BE VACUUMED WHEN DRY. DISMANTLING OF PLASTIC DYKE BEGINS.

0630 PM: DYKE HAS BEEN DISMANTLED AND PLASTIC SHEETING HAS BEEN BAGGED. WASHING OF SIDEWALK AND STREET BEGINS

0700PM: SIDEWALK AND STREET CLEAN UP HAS BEEN COMPLETED.

MONDAY NOVEMBER 11 2002

THE CLEANING OF STORE FRONT WINDOWS BEHIND THE METAL ROLL DOWN GATES WAS CONDUCTED TODAY. AT THE CONCLUSION OF THE CLEANING ACTIVITIES, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND I OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT AT THE PREMISE IS NOW COMPLETE.