

WTC Visual Survey Form BN#1001200

Premise Address: 39 John Street		
Block: 78 Lot: 35	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	Name of Building:
# of Stories:	AKA's: 72-78 Nassau Street	
Building Owner/Management Name:		Telephone Number: ()
		FAX: ()
Address:		
On Site Contact Name:		
		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	☒ 1/2 to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	☒ 1/2 to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	☒ 1/2 to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	☒ 1/2 to 1"	☐ > 1"
Facade Description: facade has visible debris					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Comments					

Date: 8/15/2002

Inspection by: Name: AP
Name: _____

Agency: DEP
Agency: _____