

WTC Visual Survey Form

Premise Address: 41-43 JOHN STREET		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: Partial Access No Access					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" of dust ☐ > 1" of dust					
Description: Partial Access No Access					
Setbacks N/A ☐					
Floor: 2nd		Debris:	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
Floor: _____		Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____		Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____		Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____		Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments					

Date: 7/17/2002

Inspection Team: Name: D. ANTZOULATOS

Agency: NYCDER

Name: _____

Agency: _____

ENTERED