

WTC Visual Survey Form

1075701

Premise Address: <i>41 John St</i>			<i>(2 stories)</i>		
Block: <i>78</i>	Residential ☐ Commercial ☐	Name of Building:			
Lot: <i>7502</i>	Mix Use ☒ Other ☐				
# of Stories: <i>45</i>	AKA's: <i>41-43 John St.</i>				
Building Owner/Management:			Telephone Number: ()		
Name: <i>Condominiums</i>			FAX: ()		
Address:					
On Site Contact:					
Name:			Telephone Number: ()		
Building Owner Management Activities					
Interior Survey Performed ☐ Yes ☐ No					
Exterior Survey Performed ☐ Yes ☐ No					
General Clean Up ☐ Yes ☐ No Locations: _____					
ACM Clean Up ☐ Yes ☐ No Locations: _____					
Air Monitoring ☐ Yes ☐ No Locations: _____					
Copies of All Reports and Data Requested ☐ Yes					

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <i>Brick windows etc is clean and windows</i>					
Roof					
<i>Light dust</i>					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" of dust ☐ > 1" of dust.					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Comments <i>I could not gain access into the bldg and the roof</i>					

Date: *3/2/2002*Inspection Team: Name: *AL*

Agency: _____

Name: _____ Agency: _____