

Asbestos Inspection Report

Premise No. 44 JOHN STREET					Inspection Date: As NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 6T	Lot 30	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type CHURCH		Basis of Inspection WTC Survey		Photos Taken (Yes/ No)
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: As NOTED		
THURSDAY SEPTEMBER 12 2002						
THE CLEAN UP PROJECT AT THE CHURCH BEGINS IN THE EAST COURTYARD AND THE REAR OF THE CHURCH. A REMOTE DECONTAMINATION UNIT WAS ERECTED IN THE WEST COURTYARD. AIR MONITORING (SAMPLING) FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY FESTY OSEMWEGIE (CERTIFICATE # PII EXP 01/03).						
FRIDAY SEPTEMBER 13, 2002						
THE CLEAN UP AT THE EAST COURTYARD IS COMPLETED (EAST FACADE CLEANED, COURTYARD FLOOR AND REMOVAL OF SOIL FROM GARDEN). THE CLEAN UP IN THE WEST COURTYARD AND THE ROOF BEGINS. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY FESTY OSEMWEGIE OF WARREN & PANZER ENGINEERS.						
SATURDAY SEPTEMBER 14 2002						
THE CLEAN UP AT THE WEST COURTYARD (WEST FACADE CLEANED COURTYARD FLOOR CLEANED AND REMOVAL OF SOIL FROM GARDEN) IS COMPLETED. THE CLEAN UP OF NORTH (JOHN STREET) FACADE WAS CONDUCTED TODAY. A PLASTIC DYKE WAS CONSTRUCTED TO COLLECT WATER RUN OFF. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY FESTY OSEMWEGIE. AT THE COMPLETION OF TODAY'S CLEAN UP ACTIVITIES, I CONDUCTED A VISUAL INSPECTION OF ALL CLEANED WORK AREAS. NO VISIBLE WTC DEBRIS WAS OBSERVED. THE CLEAN UP PROJECT AT THIS PREMISE IS NOW COMPLETE.						

RL