NYC 9/11 Public Portal Document

WTC Visual Survey Form

BN # 1001110

Premise Address: 44 JOHN STREET

Block: 67 **Lot:** 30	Residential ☐ Commercial ☐ Mix Use ☐ Other ☒ CHURCH	**Name of Building:** OLD JOHN STREET UNITED METHODIST CHURCH
# of Stories:	**AKA's:**	

Building Owner/Management: Telephone Number: ( )
Name: FAX: ( )

Address: 44 JOHN STREET NY NY 10038 -3714

On Site Contact: REVEREND
Name: REV. JAMES McGRAW Telephone Number: (212) 269-0014

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No
Exterior Survey Performed ☐ Yes ☐ No
General Clean Up ☐ Yes ☐ No Locations: _____
ACM Clean Up ☐ Yes ☐ No Locations: _____
Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"

Facade Description:

Roof

Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"
Description: DEBRIS IS COLLECTED ON THE FLAT (HORIZONTAL) LEDGE OF THE ROOF

Setbacks N/A ☒

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 07 / 03 /2002 Inspection Team: Name: DA & R. RAMMOHAN Agency: NYC DEP
Name: _____ Agency: _____