

WTC Visual Survey Form

1001127

Premise Address: <u>90 JOHN STREET</u>	
Block: <u>64</u> Lot: <u>7502</u>	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐
Name of Building:	
# of Stories:	AKA's: <u>15-23 PLATT STREET 20-24 GOLD STREET</u>
Building Owner/Management: Name: Telephone Number: () FAX: ()	
Address:	
On Site Contact: Name: Telephone Number: ()	
Building Owner Management Activities	
Interior Survey Performed ☐ Yes ☐ No	
Exterior Survey Performed ☐ Yes ☐ No	
General Clean Up ☐ Yes ☐ No Locations: _____	
ACM Clean Up ☐ Yes ☐ No Locations: _____	
Air Monitoring ☐ Yes ☐ No Locations: _____	
Copies of All Reports and Data Requested ☐ Yes	

Visual Inspection Results:

Facade:		Inspected		Debris	
North	☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: _____					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					
<u>Results communicated via telephone PL</u>					

Date: 8/28/2002Inspection Team Name: D. ANTZOUKATOSAgency: NVCDEP

Name: _____

Agency: _____

ENTERED

WTC Visual Survey Form

Premise Address: 90 JOHN STREET		
Block: 69 Lot: 7502	Residential ☐ Commercial ☐ Mix Use ☒ Other ☐	Name of Building:
# of Stories: 34	AKA's: 100, 102, 104, 106, 108 AND 110 JOHN STREET	
Building Owner/Management: NEW MARK Name: RICHARD FRANCO		Telephone Number: PII FAX: (212) 594-7238
Address: PII		
On Site Contact: Name: HUGO (CHIEF ENGINEER) Telephone Number: ()		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: ROOF, FACADES, SETBACKS, PATIOS		
ACM Clean Up ☐ Yes ☐ No Locations:		
Air Monitoring ☐ Yes ☐ No Locations:		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected ☒ Yes ☐ No	Debris ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: 					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: 					
Setbacks N/A ☐					
Floor:		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor:		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor:		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor:		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor:		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments 					

Date: 08 / 28 / 2002

Inspection Team: Name: DA / A020
Name:Agency: DEP
Agency: