

ASBESTOS INSPECTION REPORT

PAGE 1 OF

|                               |       |                |                              |                              |         |                       |  |
|-------------------------------|-------|----------------|------------------------------|------------------------------|---------|-----------------------|--|
| EMISE NO                      |       | STREET         |                              |                              |         | INSPECTION DATE       |  |
| 55 John Street                |       |                |                              |                              |         | 10/17/02              |  |
| DOOR                          | ZIP   | BORO CODE      | BLOCK                        | LOT                          | SQUAD # | BADGE #               |  |
| FACADE COURT                  | 10038 | 1              | 78                           | 4                            | 1       | AD10                  |  |
| SPECTRUM                      |       | BLDG TYPE      | BASIS OF INSPECT             |                              |         | PHOTOS TAKEN YES / NO |  |
| PLUMPTRE                      |       |                | TRU 1481 MNO2                |                              |         |                       |  |
| CONTRACTORS NAME              |       |                |                              | SAMPLE NO.                   |         |                       |  |
| FIBER CONTROL                 |       |                |                              |                              |         |                       |  |
| ADDRESS                       |       |                |                              | SAMPLE NO.                   |         |                       |  |
| 3010 BURNS AVE                |       |                |                              |                              |         |                       |  |
| CITY                          |       |                |                              | SAMPLE NO.                   |         |                       |  |
| WANTAGH                       |       |                |                              |                              |         |                       |  |
| STATE                         | ZIP   | PHONE          | OWNERS NAME                  |                              |         |                       |  |
| N.Y                           | 11793 | (516) 781-3000 | WILLIAM ST. Assoc % Clean up |                              |         |                       |  |
| LABORATORY NAME               |       |                |                              | ADDRESS                      |         |                       |  |
| WARREN & PANZER ENGINEERS, PC |       |                |                              | 123 William St               |         |                       |  |
| CITY                          |       |                |                              | CITY                         |         |                       |  |
| N.Y                           |       |                |                              | NY                           |         |                       |  |
| ADDRESS                       |       |                |                              | STATE                        |         |                       |  |
| 228 E. 45TH ST                |       |                |                              | N.Y                          |         |                       |  |
| STATE                         |       |                |                              | ZIP                          |         |                       |  |
| N.Y                           |       |                |                              | 10038                        |         |                       |  |
| PHONE                         |       |                |                              | PHONE                        |         |                       |  |
| (212) 922-0077                |       |                |                              |                              |         |                       |  |
| CONTACT PERSON:               |       |                |                              | TIME OF INSPECTION FROM: TO: |         |                       |  |
|                               |       |                |                              | 6:00 am/pm TO: 12:45 pm/pm   |         |                       |  |
| INSPECTION DISCLOSED:         |       |                |                              |                              |         |                       |  |

The Cleanup of the facade was done from inside due to inability to set up scaffold on the roof because of the new Cooper roof.

17th and 16th floors were completed on 10/17/02 and no visual debris observed after the cleanup.

On 10/18, 16th, 15th, 14th were ~~all~~ completed without visual debris observed after the cleanup.

10th, 9th, 8th and 7th floors were completed on 10/19 and no visual debris observed after cleanup.

The lower floors were completed on 10/23 including the courtyard. Visual inspections were done on all remaining floors including the 12th floor and no visual debris observed.

|       |             |  |  |  |  |                      |
|-------|-------------|--|--|--|--|----------------------|
| NOV # | INFRACTIONS |  |  |  |  | RESULT CODE          |
|       |             |  |  |  |  | 5                    |
| NOV # |             |  |  |  |  | SUPERVISORS INITIALS |
|       |             |  |  |  |  | Pl.                  |

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access 4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 309

FILE