

WTC Visual Survey Form

Premise Address: 55 JOHN STREET		
Block: 78	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building:
Lot:		
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name: BILL HODEL		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1" ☐ > 1"
Facade Description: _____ _____					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____ _____					
Setbacks N/A ☐					
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments _____ _____ _____ _____					

Date: 08 / 30 / 2002

Inspection Team: Name: DA / A020

Agency: DEP

Name: _____ Agency: _____

ENTERED