

WTC Visual Survey Form

1001979

Premise Address: 31-53 Leonard St

Block: 177 **Residential** ☒ **Commercial** ☐ **Name of Building:** _____

Lot: 7 **Mix Use** ☐ **Other** ☐ _____

of Stories: _____ **AKA's:** _____

Building Owner/Management: _____ **Telephone Number:** () _____

Name: _____ **FAX:** () _____

Address: _____

On Site Contact: _____ **Telephone Number:** () _____

Name: _____

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☐ Yes ☐ No **Locations:** _____

ACM Clean Up ☐ Yes ☐ No **Locations:** _____

Air Monitoring ☐ Yes ☐ No **Locations:** _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: Cleaned

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: _____

Setbacks N/A ☒

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 5/17/2002

Inspection Team: Name: Al

Agency: _____

Name: _____

Agency: _____