WTC Visual Survey Form

10/1972

Premise Address: 57 Leonard St

Block: 177 **Lot:** 5	**Residential** ☒ **Commercial** ☐ **Mix Use** ☐ **Other** ☐	**Name of Building:**
# of Stories:	**AKA's:**	

Building Owner/Management: **Telephone Number:** ( )
Name: **FAX:** ( )
Address:

On Site Contact:
Name: **Telephone Number:** ( )

Building Owner Management Activities

- Interior Survey Performed ☐ Yes ☐ No
- Exterior Survey Performed ☐ Yes ☐ No
- General Clean Up ☐ Yes ☐ No Locations: _____
- ACM Clean Up ☐ Yes ☐ No Locations: _____
- Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: Cleaned

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"
Description: _____

Setbacks N/A ☒

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 5/17/2002 **Inspection Team: Name:** AL **Agency:** _____
Name: _____ **Agency:** _____

ENTERED