

## WTC Visual Survey Form

**Premise Address:** 250, Church St

**Block:** Residential ☐ Commercial ☒ **Name of Building:** \_\_\_\_\_  
**Lot:** Mix Use ☐ Other ☐

**# of Stories:** 59 **AKA's:** Leonard St

**Building Owner/Management:** MC HRA **Telephone Number:** ( ) \_\_\_\_\_  
**Name:** \_\_\_\_\_ **FAX:** ( ) \_\_\_\_\_

**Address:** \_\_\_\_\_

**On Site Contact:** John Cosme (Engineer) **Telephone Number:** ( ) \_\_\_\_\_  
**Name:** \_\_\_\_\_

**Building Owner Management Activities**  
 Interior Survey Performed ☐ Yes ☐ No  
 Exterior Survey Performed ☐ Yes ☐ No  
 General Clean Up ☐ Yes ☐ No **Locations:** \_\_\_\_\_  
 ACM Clean Up ☐ Yes ☐ No **Locations:** \_\_\_\_\_  
 Air Monitoring ☐ Yes ☐ No **Locations:** \_\_\_\_\_

**Copies of All Reports and Data Requested** ☐ Yes

## Visual Inspection Results:

**Facade:**

|       |                              | Inspected                                                | Debris                                         |                                  |                               |
|-------|------------------------------|----------------------------------------------------------|------------------------------------------------|----------------------------------|-------------------------------|
| North | <input type="checkbox"/> N/A | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| South | <input type="checkbox"/> N/A | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| East  | <input type="checkbox"/> N/A | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| West  | <input type="checkbox"/> N/A | <input type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |

**Facade Description:** Cleaned

---

**Roof**

**Debris:** ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

**Description:** \_\_\_\_\_

---

**Setbacks** N/A Cleaned

|              |                                                        |                                  |                               |
|--------------|--------------------------------------------------------|----------------------------------|-------------------------------|
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |

**Comments**

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Date: 5/17/2002Inspection Team: Name: AL

Agency: \_\_\_\_\_

Name: \_\_\_\_\_

Agency: \_\_\_\_\_