

WTC Visual Survey Form

BN# 1001085

Premise Address: <u>59-65 Liberty St</u>		
Block: <u>64</u>	Residential ☐ Commercial ☒	Name of Building:
Lot: <u>9</u>	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management: <u>International</u> Telephone Number: ()		
Name: <u>Commercial Bank of Chicago</u> FAX: ()		
Address:		
On Site Contact:		
Name: <u>Joe Azzopardi</u>		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☒ Yes ☐ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☐ Yes ☒ No	Locations: _____	
ACM Clean Up ☐ Yes ☒ No	Locations: _____	
Air Monitoring ☐ Yes ☒ No	Locations: _____	
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Facade Description: <u>NO visible debris on windows and facade</u>					
Roof					
Debris: ☒ No Visible /Fine Layer ^{Light dust} ☐ 1/2 to 1" of dust ☐ > 1" of dust.					
Description: _____					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Comments					

Date: 02/15/2002Inspection Team: Name: Alphonso flurba Agency: NYCDET
Name: _____ Agency: _____