

Visual Inspection Results:

Facade: North ☐ N/A South ☐ N/A East ☐ N/A West ☐ N/A		Inspected ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		Debris ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1" ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1" ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1" ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"			
Facade Description: 							
Roof							
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"							
Description:							
Setbacks							
N/A ☐							
Floor: <u>2</u>	Debris: ☒ No Visible/Fine Layer	Debris: ☒ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer		
Floor: _____	Debris: ☒ No Visible/Fine Layer	Debris: ☒ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer		
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer		
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer		
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer		
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer	Debris: ☐ No Visible/Fine Layer		
Comments 							

Date:

Inspection Team: Name:
Name:

Agency:
Agency: