

WTC Visual Survey Form

1066447

Premise Address: 6 Hanson St

Block: 181 **Residential** ☐ **Commercial** ☐ **Name of Building:** Landmark
Lot: 7503 **Mix Use** ☐ **Other** ☐

of Stories: 2-6 **AKA's:** 2-6 Hanson St, 187-91 Hudson Street

Building Owner/Management: N.Y. Mercantile Exchange **Telephone Number:** ()
Name: N.Y. Mercantile Exchange **FAX:** ()
Address:

On Site Contact: **Telephone Number:** ()
Name:

Building Owner Management Activities
 Interior Survey Performed ☐ Yes ☐ No
 Exterior Survey Performed ☐ Yes ☐ No
 General Clean Up ☐ Yes ☐ No **Locations:**
 ACM Clean Up ☐ Yes ☐ No **Locations:**
 Air Monitoring ☐ Yes ☐ No **Locations:**

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"

Facade Description:

Roof

Debris: ☒ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1"

Description:

Setbacks ☐ N/A

Floor: <u></u>	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: <u></u>	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: <u></u>	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: <u></u>	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: <u></u>	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"

Comments

Date: 5/11/2002

Inspection Team: Name: CARL
 Name:

Agency:
 Agency:

ENTERED