

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date 03/22/2002 12:36 PM

Submitted By

Page 1

Service # 422163
Problem BWTCH WTC RELATED (HOT LINE)
Address 12 JOHN ST 1
10038
Cross Streets BROADWAY
NASSAU ST
Compass Direction
Building ID 10011 Block 00065 Lot 0020 CMBD 101

Location
Area District
Sub-Area 101 Parcel

of Calls 1 Duration of Call 00:00 Call Date 03/19/2002 12:12
Taken By 7145 MAYFIELD, CHERELLE
Responsibility BHZ BANHAZMAT (AIR,NOISE,HAZ.MAT)
Scheduled Date 03/20/2002 11:00 Priority
Inspector 4230 LUTCHMEDIAL, CARLSTIE Start Date 03/20/2002 11:00
Due Date Inspection Date 03/20/2002 11:00
Resolution Code B35 AIR TESTING REQUESTED (WTC) ☐ No Work Orders Required
Asset Resolution Date 03/20/2002 11:30
Avg Insp Duration ☐ Customer Contact Req
Avg Insp Days 0 Budget #
Avg Insp Hrs 0
Avg Insp Mins 0

Problem Comments DEP HAS NOT RECEIVED ANY INFORMATION FROM THE OWNER.

~~THIS COMPLAINT HAS BEEN FORWARDED TO THE ASBESTOS UNIT FOR APPROPRIATE ACTION.~~

inspection revealed that the vents were sealed. presently there was no visible dust in th eapartment or on th ewindow ledges outside. Ms Minsky said that she had cleaned the ledges herself. her concern was that she wanted DEP to test the air and wheteher dust was coming from the roof into the vent of her apartment. inspection of the roof revealed that the vent were natural air exhaust vents only. the roof was very clean and free of WTC debris. i also inspected the penthouse apartment (Apt. DP 12) of Mr. Scot Meyers. he was also concerned about dust which keeps filling up his air purifier. his apartment was also free of visible debris. he said that his apartment had been tested and was free of ACM.

Initial Caller

Last Name Title MS
First Name, MI
Address
City, State/Province, ZIP/PC
☐ Foreign
Day Phone Evening Phone Call Date 03/19/2002 12:12
Reference #

Caller Comments GRATES NEAR CELLING HAVE NOT BEEN CLEAN AND FEELS THAT DUST IS ACCUMMALATING. REFERRED TO BWTCH BY ASSEMBLEMAN SHELDON SILVER. ALSO BUILDING #11 MAIDEN LANE HAS NOT BEEN CLEAN. ALSO FEELS THE DUST FROM 11 MAIDEN LANE IS GOING INTO HER APARTMENT.

Work Order #	Activity	Asset	Act Type	Act Group	Initiated	Scheduled	Completed	Source	Maint Type
Priority	Problem	Project	Fr Type	Unit ID		To Type	Unit ID		

There are no work orders for this service number

Assets	From Type	Unit ID	To Type	Unit ID	#	Qualifier
--------	-----------	---------	---------	---------	---	-----------