

WTC Visual Survey Form

Premise Address: 12 JOHN STREET		
Block:	Residential ☒ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	ANDERSON BLDG.
# of Stories:	AKA's:	
Building Owner/Management Name:		Telephone Number: ()
Address:		FAX: ()
On Site Contact Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
		Inspected	Debris
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Facade Description:			
HEAVY DEBRIS IS LOCATED ON STORE AWNINGS AND ON THE 2ND FLOOR LEDGE. SOUTH FACADE BELOW SET BACK ROOF HAS HEAVY DEBRIS			
Roof			
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"			
Description: NOT ACCESSIBLE ON DATE OF THIS SURVEY			
Setbacks N/A ☐			
Floor:	3rd	Debris:	☐ No Visible/Fine Layer ☒ ½ to 1" ☐ > 1"
Floor:	_____	Debris:	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor:	_____	Debris:	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor:	_____	Debris:	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor:	_____	Debris:	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Comments			

Date: 08 / 04 / 2002

Inspection Team: Name: DA / A020

Agency: DEP

Name: _____

Agency: _____