

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368**
JOEL A. MIKLE, SR., P.E.
COMMISSIONER

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: WTC071302

Date Sampled: 7/13/2002

Premise: 15 John St

Boro: Mn

Time: 11 am/pm

Inspector: CARL LUTCHMEDIAN
Print

Signature

Turnaround Time: Immediate ☒ 24 Hours [] 48 Hours [] 1 Week []

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20713/A058011	Fibrous ⊕	Westside Louver 3 level ↓ Roof	648
2. 20713/A058012		" Window ledge 5 Level " "	649
3. 20713/A058013		" " " 5 " ↓ Roof	650
4. 20713/A058014		" " " 7 Level ↓ Roof	651
5. 20713/A058015		" " " 7 " " "	652
6. 20713/A058016		Top AC (int) 7 level " "	653
7. 20713/A058017		Facade Surface 7 " " "	654
8. 20713/A058018		Top Elec. Cable 7 " " "	655
9. 20713/A058019		" " " " " "	656
10. 20713/A058020		Facade Ledge 7 level ↓ Roof	657

ANALYSIS REQUESTED: Asbestos PLM []

Asbestos TEM []

Lead []

Date	Time	Accepted By	Comments
1. 7/13/02	12:30 <u>pm</u>	Print <u>E. Brutus</u>	<u>Transport and Safe custody</u>
		Sign <u>E. Brutus</u>	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

DEP ACLP REV5/00