

ASBESTOS INSPECTION REPORT

EMISE NO.		STREET				INSPECTION DATE	
17		John Street				10/7/02	
DOOR	ZIP	BORO CODE	BLOCK	LOT	SQUAD #	BADGE #	
Roof		1	79	10	1	AD10	
SPECTOR		BLDG TYPE	BASIS OF INSPECT.			PHOTOS TAKEN YES / NO	
127 Benson Plumped			TRU 1529m				
CONTRACTORS NAME				SAMPLE NO.			
FIBER CONTROL							
ADDRESS				CITY			
3010 BURNS AVE				WANTAGH			
STATE				PHONE			
N.Y. ZIP 11793				(616) 781-3000			
LABORATORY NAME				OWNERS NAME			
WARREN & PAWEER ENGINEERS, PC				17 John Street LLC			
ADDRESS				CITY			
328 E. 45TH ST				N.Y.			
STATE				PHONE			
N.Y. ZIP 10017				(212) 922-0077			
CONTACT PERSON:				TIME OF INSPECTION FROM: 9:30 am TO: 6:00 pm			
INSPECTION DISCLOSED:							

The Cleanup of the roof started on 10/7/02 with the lifting of concrete slabs which cover 3/4 of the roof. Both roof and concrete slabs were cleaned and the cleanup was completed on 10/11/02. Visual inspection was done after the cleanup and no visible debris observed.

NOV #	INFRACTIONS	RESULT CODE
		5
NOV #		SUPERVISORS INITIALS
		PL

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access 4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 309

FILE