

Asbestos Inspection Report

Premise No. 20 JOHN STREET					Inspection Date: As NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 65	Lot 22	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken <u>Yes</u> / No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: As NOTED		
SUNDAY OCTOBER 6 2002 (0600AM - 1100AM)						
THE CLEAN UP OF THE NORTH FACADE OF THE PREMISE WAS CONDUCTED TODAY. A PLASTIC DYKE WAS CONSTRUCTED TO COLLECT RUN OFF WATER. A DECONTAMINATION TRUCK WAS UTILIZED FOR WORKER DECONTAMINATION. AIR SAMPLING WAS PERFORMED BY CHETRAM PAMRAJ (CERTIFICATE # AH 98-19842 EXP 01/03) OF WARREN & PANZER. THE AIR SAMPLES WERE RUN ON THE OPPOSITE SIDEWALK. AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES I CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND OBSERVED NO VISIBLE WTC DEBRIS.						
THURSDAY OCTOBER 10 2002 (0800AM - 0800PM)						
THE CLEAN UP OF THE REAR FACADE (SOUTH FACADE) WAS CONDUCTED TODAY. AIR SAMPLING WAS PERFORMED BY FESTY OSEMUEGIE OF WARREN & PANZER (CERTIFICATE # AH 01-01030 EXP 01/03). THE AIR SAMPLES WERE RUN ON THE ROOF OF 18 JOHN STREET.						
THURSDAY OCTOBER 17 2002 (0800AM - 0800PM)						
THE CLEAN UP OF THE ROOF OF THE PREMISE WAS CONDUCTED TODAY. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP PROJECT WAS PERFORMED BY IDRIS IDOLU (CERTIFICATE # AH-02 11201 EXP 03/03). UPON COMPLETION OF THE CLEAN UP ACTIVITIES I CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND I OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT AT THE PREMISE IS NOW COMPLETE.						
NOTE: THE CLEAN UP OF THE NORTH FACADE OF 20 JOHN ST & THE CLEANUP OF THE NORTH FACADE OF 18 JOHN ST OCCURRED SIMULTANEOUSLY. FOR THE PURPOSES OF AIR MONITORING, THE FACADES OF THESE TWO BUILDINGS WERE TREATED AS ONE WORK AREA.						

RL